

Location

Overall Good:

Signs/Marker:

Type	WELLHEAD		
Comment:	Signage at wellhead is inaccurate, shows Synergy Resources info. See attached photos		
Corrective Action:	Install sign to comply with Rule 210.b.	Date:	06/10/2017

Emergency Contact Number:

Comment:

Corrective Action:

Date: 06/10/2017

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

Type					corrective date
Type: Pump Jack	# 1				
Comment:					
Corrective Action:					Date:
Type: Prime Mover	# 1				
Comment:	Natural gas fired engine				
Corrective Action:					Date:

Venting:

Yes/No			
Comment:			
Corrective Action:			Date:

Flaring:

Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities

Facility ID: 202081 Type: WELL API Number: 001-07486 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

COGCC Comments

Comment	User	Date
Well is commingled to Zarlengo #1 (001-006795) battery, all battery equipment is identified on it's field inspection report DOC#667601607	kraicha	05/11/2017

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401281323	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4145341
667601614	Location Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4145334