

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/11/2017

Submitted Date:

05/18/2017

Document Number:

673404637**FIELD INSPECTION FORM**Loc ID 313150 Inspector Name: Waldron, Emily On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 16700Name of Operator: CHEVRON USA INCAddress: 6301 DEAUVILLE BLVDCity: MIDLAND State: TX Zip: 79706**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:8 Number of Comments5 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

| Contact Name | Phone | Email | Comment |
|---------------|----------------|--------------------------|---------------------------------|
| Leonard, Mike | | mike.leonard@state.co.us | |
| Fillpot, Greg | (307) 299-3829 | gfillpot@hilcorp.com | All Inspections |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|------------------|-------------|
| 262836 | WELL | PR | 02/21/2002 | OW | 081-07084 | VAN SCHAICK C 10 | PR |

General Comment:

LocationOverall Good: ☒

| | | | |
|----------------------|---|-------|------------|
| Signs/Marker: | | | |
| Type | BATTERY | | |
| Comment: | Sign not posted or information inaccurate at well(s) or battery. Chevron and Chevron emergency number on battery sign. | | |
| Corrective Action: | Install sign to comply with Rule 210.b. | Date: | 06/16/2017 |
| Type | WELLHEAD | | |
| Comment: | Sign not posted or information inaccurate at well(s) or battery. Chevron on wellhead sign. | | |
| Corrective Action: | Install sign to comply with Rule 210.b. | Date: | 06/16/2017 |
| Type | TANK LABELS/PLACARDS | | |
| Comment: | Sign not posted or information inaccurate on tanks or containers Chevron and Chevron emergency number still on tanks/containers. | | |
| Corrective Action: | Install sign to comply with Rule 210.d. | Date: | 06/16/2017 |

Emergency Contact Number:

Comment: Sign not posted or information inaccurate
No emergency contact information for Hilcorp. All contact information is Chevron.

Corrective Action: Install sign to comply with Rule 210.e.

Date: 06/16/2017

Overall Good: ☒

| | | | |
|----------------|------|--------|--|
| Spills: | | | |
| Type | Area | Volume | |

In Containment: No

Comment: ☐ Multiple Spills and Releases?

| | | |
|---------------------------------|-------|-----------------|
| Equipment: | | corrective date |
| Type: Horizontal Heater Treater | # 1 | |
| Comment: | | |
| Corrective Action: | Date: | |
| Type: Pump Jack | # 1 | |
| Comment: | | |
| Corrective Action: | Date: | |
| Type: Gas Meter Run | # 1 | |
| Comment: | | |
| Corrective Action: | Date: | |
| Type: Bird Protectors | # | |
| Comment: | | |
| Corrective Action: | Date: | |
| Type: Deadman # & Marked | # 4 | |
| Comment: | | |
| Corrective Action: | Date: | |

Tanks and Berms:

| | | | | | | |
|--------------------|---|----------|------------------|---------|-----------------------|--|
| Contents | # | Capacity | Type | Tank ID | SE GPS | |
| CONDENSATE | 2 | 400 BBLs | HEATED STEEL AST | | 40.971770,-108.666770 | |
| Comment: | | | | | | |
| Corrective Action: | | | | | Date: | |

Paint

| | | |
|------------------|----------|--|
| Condition | Adequate | |
| Other (Content) | | |
| Other (Capacity) | | |
| Other (Type) | | |

Berms

| | | | | | |
|--------------------|----------|---------------------|---------------------|-------------|-------|
| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance | |
| Earth | Adequate | | | Adequate | |
| Comment: | | | | | |
| Corrective Action: | | | | | Date: |

Venting:

| | | | |
|--------------------|----|--|-------|
| Yes/No | NO | | |
| Comment: | | | |
| Corrective Action: | | | Date: |

Flaring:

| | | |
|--------------------|--|-------|
| Type | | |
| Comment: | | |
| Corrective Action: | | Date: |

| | | | | |
|-----------------------------|------------|-----------------------|------------|------------------|
| Inspected Facilities | | | | |
| Facility ID: 262836 | Type: WELL | API Number: 081-07084 | Status: PR | Insp. Status: PR |
| Producing Well | | | | |
| Comment: | | | | |
| Corrective Action: | | | | Date: |

Reclamation - Storm Water - Pit**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|---|-----------------|-------------------------|-----------------------|--|--------------------------|---|
| | | | | Material Handling And Spill Prevention | Fail | Lube oil at wellhead without containment. |
| <p>Comment: No apparent soil migration; erosion or soil movement. Lube oil at wellhead without containment.</p> <p>Corrective Action: Install or repair required BMPs per Rule 1002.f. Refer to the 1002.f guidance document for further details.</p> | | | | | | |
| | | | | | | Date: 06/16/2017 |

Pits: ☐ NO SURFACE INDICATION OF PIT

COGCC Comments

| Comment | User | Date |
|--|----------|------------|
| Form 10 transfer from Chevron to Hilcorp approved 3/1/2017 document number 401165724. Hilcorp name is on battery signs, but there is no emergency contact information for Hilcorp on location. Chevron's name and emergency number remain prominent on tanks/containers and signs on entirety of location. | waldrone | 05/18/2017 |

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|-------------------|---|
| 673404638 | Inspection Photos | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4150627 |