

Inspection Photos - 2017 Flowline NTO
Inspection 1000' Buffer
Location Name: Jones 1-11
API: 05-107-06093



Photo 1. Wellhead with 2 steel risers. 1" on left 2" on right.



Photo 2. 1" steel flowline from wellhead to separator.

Inspection Photos - 2017 Flowline NTO
Inspection 1000' Buffer
Location Name: Jones 1-11
API: 05-107-06093



Photo 3. Separator for casing gas with 2 - 1" poly lines. One going to propane tank one going to pump jack motor.



Photo 4. 2 - 1" poly lines extending from separator to propane tank and pump jack motor.

Inspection Photos - 2017 Flowline NTO
Inspection 1000' Buffer
Location Name: Jones 1-11
API: 05-107-06093



Photo 5. Lube oil leaking from side of pump jack motor.



Photo 6. Oil leaking from rear of pump jack motor.

Inspection Photos - 2017 Flowline NTO
Inspection 1000' Buffer
Location Name: Jones 1-11
API: 05-107-06093



Photo 7. 2" steel riser at separator.



Photo 8. 3" steel riser at separator.

Inspection Photos - 2017 Flowline NTO
Inspection 1000' Buffer
Location Name: Jones 1-11
API: 05-107-06093



Photo 9. 3" and 4" steel risers at manifold between tank and separator.



Photo 10. Stained soil at tank base. 2", 3" 4" steel flowlines.

Inspection Photos - 2017 Flowline NTO
Inspection 1000' Buffer
Location Name: Jones 1-11
API: 05-107-06093



Photo 11. 2 – 4" steel flowlines at tank load out at base of hill.



Photo 12. 1 – 4 " steel flowline at battery load out.

Inspection Photos - 2017 Flowline NTO
Inspection 1000' Buffer
Location Name: Jones 1-11
API: 05-107-06093



Photo 13. 2 – 4" steel flowlines at tanks.



Photo 14. 4" steel flowline from uphill at wellhead.