

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/12/2016

Submitted Date:

04/24/2017

Document Number:

679100023**FIELD INSPECTION FORM**
 Loc ID 438250 Inspector Name: KUBECZKO, DAVE On-Site Inspection ☐ 2A Doc Num: _____
Operator Information:OGCC Operator Number: 10598Name of Operator: SANDRIDGE EXPLORATION & PRODUCTION LLCAddress: 123 ROBERT S KERR AVECity: OKLAHOMA CITY State: OK Zip: 73102**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:1 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Laird, Spence	405-429-6518	slaird@sandridgeenergy.com	

General Comment:

Date of Inspection: 08-12-16

Type of Inspection: Construction, Containment, Stormwater

Location Name: Evans 0780 21 Pad;

Location ID #: 438250

Observed site preparation for and construction of well pad and large centralized tank battery site on 08-12-16;

Construction stormwater BMPs for well pad (perimeter berm, diversion trenches, silt fences, straw wattles, rock check dams, and other spill stormwater control equipment) and access road (borrow ditch with large rock check dams for sediment control) are in-place and these stormwater controls indicate no offsite migration of fluids or sediment.

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401283803	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4147535