

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/12/2016

Submitted Date:

04/24/2017

Document Number:

679100024

FIELD INSPECTION FORM

Loc ID 446527 Inspector Name: KUBECZKO, DAVE On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10598
Name of Operator: SANDRIDGE EXPLORATION & PRODUCTION LLC
Address: 123 ROBERT S KERR AVE
City: OKLAHOMA CITY State: OK Zip: 73102

Findings:

- 1 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Laird, Spence	405-429-6518	slaird@sandridgeenergy.com	

General Comment:

Date of Inspection: 08-12-16
Type of Inspection: Construction, Containment, Stormwater, Drilling
Location Name: Ray Ranch 0780 16 Pad;
Location ID #: 446527
Observed site preparation for and construction of well pad and large centralized tank battery site on 08-12-16;
Construction stormwater BMPs for well pad (perimeter berm, diversion trenches, silt fences, straw wattles, rock check dams, and other spill stormwater control equipment) and access road (borrow ditch with large rock check dams for sediment control) are in-place and these stormwater controls indicate no offsite migration of fluids or sediment.
Observed drilling operations of well Evans 0780 8-21H, API 05-057-06565; drilling operations conducted in accordance with Form 2A COAs.

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401283804	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4147536