

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/26/2016

Submitted Date:

04/24/2017

Document Number:

679100027

FIELD INSPECTION FORM

Loc ID: 443885 Inspector Name: KUBECZKO, DAVE On-Site Inspection: 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10464
 Name of Operator: CATAMOUNT ENERGY PARTNERS LLC
 Address: 1801 BROADWAY #1000
 City: DENVER State: CO Zip: 80202

Findings:

- 1 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Nolan Redmon	720-484-2347	nredmond@catamountep.com	

General Comment:

Date of Inspection: 05-26-16
 Type of Inspection: Construction, Containment, Stormwater
 Location Name: Lamke 33-5-29 1 Pad;
 Location ID #: 443885
 Construction stormwater BMPs for well pad (perimeter berm, diversion trenches, silt fences, straw wattles, rock check dams, and other spill stormwater control equipment) and access road (borrow ditch with rock check dams for sediment control) are in-place and these stormwater controls indicate no offsite migration of fluids or sediment.
 Existing stormwater controls indicate no offsite migration of fluids or sediment to nearby Piedra River, nor the irrigation ditch south of the well pad.
 Rock-filled sediment collection basins in-place and operable.
 Overhead power lines had been lowered during drilling.

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401283809	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4147539