

Inspection Photos – 2017 Flowline NTO
Inspection
Location Name: Robidoux 13-12-89 1
API: 05-081-06986



Photo 1. Overview of location taken at the entrance facing west.

Inspection Photos - 2017 Flowline NTO
Inspection
Location Name: Robidoux 13-12-89 1
API: 05-081-06986



Photo 2. 2 -2" insulated risers at wellhead.



Photo 3. 1 -2" steel riser with no marking and no LOTO.

Inspection Photos - 2017 Flowline NTO
Inspection
Location Name: Robidoux 13-12-89 1
API: 05-081-06986



Photo 4. Misc equipment left on location.



Photo 5. Dehydrator with 2 -2" risers on each side.