

Inspection Photos – 2017 Flowline NTO  
Inspection  
Location Name: SD Federal 24-9DL  
API: 05-081-07624



**Photo 1. Overview of location taken at the entrance facing west.**

Inspection Photos - 2017 Flowline NTO  
Inspection  
Location Name: SD Federal 24-9DL  
API: 05-081-07624



Photo 2. 2 -2" steel risers at wellhead.



Photo 3. 5 - 2" steel risers inside separator shack

Inspection Photos - 2017 Flowline NTO  
Inspection  
Location Name: SD Federal 24-9DL  
API: 05-081-07624



Photo 4. 2 -2" steel risers at separator and dehydrator.



Photo 5. 1 -2" steel riser. 1 -2" steel flowline going to flare visible in background.

Inspection Photos - 2017 Flowline NTO  
Inspection  
Location Name: SD Federal 24-9DL  
API: 05-081-07624



Photo 6. 1- 2" steel flowline from tank top.



Photo 7. 2" line from left picture in background. 2 -2" steel risers from tank.