

Inspection Photos - 2017 Flowline NTO
Inspection
Location Name: Robidoux 24-3
API: 05-081-07292



Photo 1. Overview of location at entrance facing southwest.



Photo 2. 2 -2" and 1 - 3" steel risers at wellhead