

Inspection Photos – 2017 Flowline NTO
Inspection
Location Name: Robidoux 23-13
API: 05-081-06973



Photo 1. Overview of location taken at the entrance facing south.

Inspection Photos - 2017 Flowline NTO
Inspection
Location Name: Robidoux 23-13
API: 05-081-06973



Photo 2. 1 -2" steel riser and 1 -2" insulated riser at wellhead.



Photo 3. 1 -4" riser where separator used to be.

Inspection Photos - 2017 Flowline NTO
Inspection
Location Name: Robidoux 23-13
API: 05-081-06973



Photo 4. 1 – 4” insulated flowline at compressor.



Photo 5. 2 -1” insulated risers at compressor corner.

Inspection Photos - 2017 Flowline NTO
Inspection
Location Name: Robidoux 23-13
API: 05-081-06973



**Photo 6. 1 -6" insulated flowline from tank. 1 -
4"insulated flowline from meter run.**



Photo 7. 1 -6" insulated flowline.

Inspection Photos - 2017 Flowline NTO
Inspection
Location Name: Robidoux 23-13
API: 05-081-06973



Photo 8. 2 -4" insulated flowlines going into 6" insulated line at base.



Photo 9. 1 -2" insulated flowline changing to poly line at tank base.

Inspection Photos - 2017 Flowline NTO
Inspection
Location Name: Robidoux 23-13
API: 05-081-06973



Photo 10. 1 -2" poly flowline. 1 -2" steel flowline.



Photo 11. Poly and steel line from left photo. Poly line from tank. No point A identified for steel line.