

Inspection Photos – 2017 Flowline NTO
Inspection
Location Name: Robidoux 13-7
API: 05-081-07232



Photo 1. Overview of location taken at the entrance facing northwest.

Inspection Photos - 2017 Flowline NTO
Inspection
Location Name: Robidoux 13-7
API: 05-081-07232



Photo 2. 2 -2" insulated risers at wellhead.



Photo 3. 2 – 2" insulated risers at tank.
NFPA diamond still only for produced water.