



photo 1: Facing southwest toward former location.



photo 2: Facing north at the location.



photo 3: A cable was found extending out of the ground which was cut off below ground during this inspection.



photo 4: After the cable was removed.