

**Inspection Photos**  
**Location Name: Lot Holdings 8-12**  
**API: 05-123-20319**



**Produced water vault load line**



Inspection Photos  
Location Name: Lot Holdings 8-12  
API: 05-123-20319



Production facility



Drain valve riser

**Inspection Photos**  
**Location Name: Lot Holdings 8-12**  
**API: 05-123-20319**



**Separator inlet lines N40.32746 W-104.83070**



**1" process risers N40.32746 W-104.83073**

**Inspection Photos**  
**Location Name: Lot Holdings 8-12**  
**API: 05-123-20319**



**Cut 1" poly process line N40.32746 W-104.83073**



**3" riser at crude oil tank N40.32741 W-104.83102**

**Inspection Photos**  
**Location Name: Lot Holdings 8-12**  
**API: 05-123-20319**



**Wellhead flow line risers**



**Crude oil tank contents/capacity placard and paint**

**Inspection Photos**  
**Location Name: Lot Holdings 8-12**  
**API: 05-123-20319**



**Unused automation equipment**



**Unused dry gas tower**

