

Flowline Inspection Photos
Location Name: Purvis SE-10
API: 05-123-32473



Photo 1: Pressure test on ECD supply line



Photo 2: flowlines at wellheads

Flowline Inspection Photos
Location Name: Purvis SE-10
API: 05-123-32473



Photo 3: Flowlines in separator house



Photo 4: Risers at ECD

Flowline Inspection Photos
Location Name: Purvis SE-10
API: 05-123-32473



Photo 5: Risers at separator



Photo 6: Risers at compressor

Flowline Inspection Photos
Location Name: Purvis SE-10
API: 05-123-32473



Photo 7: Risers at tank battery