

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/12/2017

Submitted Date:

05/17/2017

Document Number:

674703934

**FIELD INSPECTION FORM**

Loc ID 335923 Inspector Name: LONGWORTH, MIKE On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 96850  
Name of Operator: TEP ROCKY MOUNTAIN LLC  
Address: PO BOX 370  
City: PARACHUTE State: CO Zip: 81635

**Findings:**

- 3 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

**Contact Information:**

Contact Name	Phone	Email	Comment
Inspection, Terra TEP	970-263-2760	COGCCInspectionReports@terraep.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
295972	WELL	PR	11/03/2008	GW	045-15871	CHEVRON TR334-23-597	SI
295973	WELL	PR	11/10/2008	GW	045-15870	CHEVRON TR 342-23-597	SI
295974	WELL	PR	11/10/2008	GW	045-15869	CHEVRON TR 542-23-597	SI
295975	WELL	PR	11/05/2008	GW	045-15868	CHEVRON TR 443-23-597	SI
295976	WELL	PR	11/11/2008	GW	045-15867	CHEVRON TR43-23-597	SI
449462	WELL	XX	03/02/2017		045-23474	CHEVRON TR 523-23-597	DG

**General Comment:**

**Location**

<b>Lease Road:</b>			
Type	Access		
comment:			
Corrective Action			Date:
Type	Main		
comment:			
Corrective Action			Date:

Overall Good:

<b>Signs/Marker:</b>			
Type	DRILLING/RECOMP		
Comment:			
Corrective Action:			Date:

Emergency Contact Number:			
Comment:	970-285-9377		
Corrective Action:			Date: _____

<b>Good Housekeeping:</b>			
Type	TRASH		
Comment:			
Corrective Action:			Date:
Type	STORAGE OF SUPL		
Comment:			
Corrective Action:			Date:

Overall Good:

<b>Spills:</b>			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			

<b>Venting:</b>			
Yes/No	NO		
Comment:			
Corrective Action:			Date:

<b>Flaring:</b>			
Type			
Comment:			
Corrective Action:			Date:

**Location Construction**

Location ID: 335923 CDP: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

**Form 2A COAs:**

**Comment:** Form 42 NOTICE CEMENT CASING 401274327

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

**Wildlife BMPs:**

**Comment:** \_\_\_\_\_

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

**Comment:** \_\_\_\_\_

**Corrective Action:** \_\_\_\_\_

Date: \_\_\_\_\_

**On Site Inspection (305):**

Surface Owner Contact Information:

Name: \_\_\_\_\_ Address: \_\_\_\_\_

Phone Number: \_\_\_\_\_ Cell Phone: \_\_\_\_\_

Operator Rep. Contact Information:

Landman Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_

Date Onsite Request Received: \_\_\_\_\_ Date of Rule 306 Consultation: \_\_\_\_\_

Request LGD Attendance: \_\_\_\_\_

LGD Contact Information:

Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_ Agreed to Attend: \_\_\_\_\_

Summary of Landowner Issues:

\_\_\_\_\_

Summary of Operator Response to Landowner Issues:

\_\_\_\_\_

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

\_\_\_\_\_

**Inspected Facilities**

Facility ID: <u>295972</u>	Type: <u>WELL</u>	API Number: <u>045-15871</u>	Status: <u>PR</u>	Insp. Status: <u>SI</u>
Facility ID: <u>295973</u>	Type: <u>WELL</u>	API Number: <u>045-15870</u>	Status: <u>PR</u>	Insp. Status: <u>SI</u>
Facility ID: <u>295974</u>	Type: <u>WELL</u>	API Number: <u>045-15869</u>	Status: <u>PR</u>	Insp. Status: <u>SI</u>
Facility ID: <u>295975</u>	Type: <u>WELL</u>	API Number: <u>045-15868</u>	Status: <u>PR</u>	Insp. Status: <u>SI</u>
Facility ID: <u>295976</u>	Type: <u>WELL</u>	API Number: <u>045-15867</u>	Status: <u>PR</u>	Insp. Status: <u>SI</u>
Facility ID: <u>449462</u>	Type: <u>WELL</u>	API Number: <u>045-23474</u>	Status: <u>XX</u>	Insp. Status: <u>DG</u>

**Well Drilling**

**Rig:** Rig Name: H&P 271 Pusher/Rig Manager: Dalen Burr  
 Permit Posted: Yes Access Sign: Yes

**Well Control Equipment:**

Pipe Ram: \_\_\_\_\_ Blind Ram: \_\_\_\_\_ Hydril Type: \_\_\_\_\_  
 Pressure Test BOP: \_\_\_\_\_ Test Pressure PSI: \_\_\_\_\_ Safety Plan: YES

**Drill Fluids Management:**

Lined Pit: \_\_\_\_\_ Unlined Pit: \_\_\_\_\_ Closed Loop: YES Semi-Closed Loop: \_\_\_\_\_  
 Multi-Well: YES Disposal Location: \_\_\_\_\_

**Comment:** Surface hole Total Depth 3013' Running in 3017.47' of 9.625" casing. Halliburton cement crew on stand by.

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
				Covering Materials	Pass	
				Material Handling And Spill Prevention	Pass	
		Gravel	Pass			
		Ditches	Pass			
		Culverts	Pass			
Ditches	Pass					
Berms	Pass					
		Compaction	Pass			
Compaction	Pass					
Gravel	Pass					

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**  NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401285517	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4149253">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4149253</a>
674703938	Drilling location photo	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4149251">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4149251</a>