

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/11/2017

Submitted Date:

05/17/2017

Document Number:

674901658**FIELD INSPECTION FORM**
 Loc ID _____ Inspector Name: _____ On-Site Inspection ☐
 Hughes, Jim _____ 2A Doc Num: _____
Operator Information:OGCC Operator Number: 96705Name of Operator: WPX ENERGY PRODUCTION LLCAddress: P O BOX 3102 MS-25-2City: TULSA State: OK Zip: 74101**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:10 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Ramos, Martha		martha.ramos@state.co.us	
Inspection, WPX	970-263-2716	COGCCInspectionReportsSanJuan@wpxenergy.com	WPX Inspection Mailbox
Fischer, Alex		alex.fischer@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
427584	PIPELINE	AL	02/03/2012		-	Tiffany Central Delivery Point (CDP)	EI

General Comment:

On May 11, 2017 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the WPX Tiffany CDP. For the most recent field inspection report of this facility, please refer to document #674901635. WPX representatives Darren Rowley and Dave Randleman were on location during this inspection.

Location			
Lease Road:			
Type	Access		
comment:	Two track dirt road.		
Corrective Action		Date:	
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
Type	OTHER		
Comment:	Carsonite pipeline markers.		
Corrective Action:		Date:	
Emergency Contact Number:			
Comment:	Carsonite pipeline markers list Williams Field Services as the emergency contact.		
Corrective Action:		Date:	
Good Housekeeping:			
Type	UNUSED EQUIPMENT		
Comment:	Miscellaneous pipeline equipment on site, including a three foot section of pipe, bolts, and wooden supports.		
Corrective Action:	Comply with Rule 603.f using the Rule 603.f guidance document for further details.	Date:	06/16/2017
Type	UNUSED EQUIPMENT		
Comment:	Three ball manifold and two pipeline risers have been determined to be unused equipment per WPX representatives. These risers and manifold were painted orange during this field inspection.		
Corrective Action:	Comply with Rule 603.f using the Rule 603.f guidance document for further details.	Date:	08/17/2017
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Equipment:			
Type: Other	# 6		corrective date
Comment:	Six pipeline risers and valve sets on/near location. Three of these have been determined to belong to WPX and shall be removed.		
Corrective Action:		Date:	
Venting:			
Yes/No			
Comment:			
Corrective Action:		Date:	
Flaring:			
Type			
Comment:			

Corrective Action:		Date:	
--------------------	--	-------	--

Inspected Facilities									
Facility ID:	427584	Type:	PIPELINE	API Number:	-	Status:	AL	Insp. Status:	EI

--

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Ditches	Pass					

Comment: Cobble lined diversion ditches.

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
<p>On May 11, 2017 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the WPX Tiffany CDP. For the most recent field inspection report of this facility, please refer to document #674901635. WPX representatives Darren Rowley and Dave Randleman were on location during this inspection.</p> <p>WPX personnel marked unused equipment with fluorescent orange spray paint. Equipment that was marked included the three ball manifold, two pipeline risers, and a steel "H" brace protective barrier. Debris/unused equipment noted in previous inspection was to be removed 5/11/17 according to WPX personnel. Reportedly, the one inch steel pipe was a domestic supply line for the landowner. Darren Rowley indicated that WPX would consult with the landowner regarding this unused equipment. This supply line is not connected to a gas supply. A one call had been reportedly made by WPX on the previous day, 5/10/17, prior to mobilizing equipment for removal of pipeline risers.</p> <p>The status of this location within the COGIS database is currently "AL". This facility has been removed from service and remaining equipment is scheduled for removal. The three other pipeline risers, located south of the access road, are reportedly the property of the pipeline operators.</p> <p>Corrective action dates noted in this inspection shall not supersede requirements of the Notice To Operators regarding flowlines. This NTO is available on the COGCC website. Please refer to this document for specific actions required and associated deadlines.</p>	hughesj	05/17/2017

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401285275	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4149040
674901659	Pipeline riser being marked for removal.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4149036
674901660	Riser with blind flange being marked for removal.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4149037
674901661	Equipment to be removed by WPX.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4149038
674901662	Pipeline risers associated with adjacent pipelines	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4149039