

FORM  
INSPRev  
X/15

## State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/03/2017

Submitted Date:

05/17/2017

Document Number:

680301936

### FIELD INSPECTION FORM

Loc ID 422414 Inspector Name: SCHURE, KYM On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Operator Information:**

OGCC Operator Number: 11001  
Name of Operator: BROWN OIL & GAS LLC  
Address: 10481 COUNTY ROAD 20.5  
City: STERLING State: CO Zip: 80751

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION  
 FOLLOW UP INSPECTION REQUIRED  
 NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

9 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**Contact Information:**

Contact Name	Phone	Email	Comment
Brown, Mark	970-522-1072	brown_oil_and_gas@hotmail.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
422433	WELL	PR	11/14/2011	OW	075-09393	CINN 44-35	PR

**General Comment:**

[Routine Site Inspection FIR](#)

**Location**

**Lease Road:**

Type	Access				
comment:	Satisfactory				
Corrective Action:				Date:	

Overall Good:

**Signs/Marker:**

Type	TANK LABELS/PLACARDS				
Comment:	Satisfactory				
Corrective Action:				Date:	
Type	WELLHEAD				
Comment:	Satisfactory				
Corrective Action:				Date:	
Type	BATTERY				
Comment:	Satisfactory				
Corrective Action:				Date:	

Emergency Contact Number:

Comment:	Satisfactory				
Corrective Action:				Date:	_____

Overall Good:

**Spills:**

Type	Area	Volume			

In Containment: No

Comment: \_\_\_\_\_

Multiple Spills and Releases?

**Equipment:**

						corrective date
Type: Ancillary equipment	# 1					
Comment:						
Corrective Action:					Date:	
Type: Gas Meter Run	# 1					
Comment:						
Corrective Action:					Date:	
Type: Vertical Separator	# 1					
Comment:						
Corrective Action:					Date:	
Type: Pump Jack	# 1					
Comment:						
Corrective Action:					Date:	
Type: Vertical Heated Separator	# 2					

Comment:			
Corrective Action:			Date:
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:			Date:
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:			Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLs	STEEL AST		40.878222,-103.365601
Comment:					
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	100 BBLs	FIBERGLASS AST		
Comment:	PW tank adjacent to lined skim pit/PW pit, staged PW handling.				
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No		
--------	--	--

Comment:			
Corrective Action:		Date:	

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 422433 Type: WELL API Number: 075-09393 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR

Corrective Action:

Date:

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Other	In Process	Other	In Process			

Comment: Continue BMP's for stormwater erosion management

Corrective Action:

Date: \_\_\_\_\_

**Pits:**  NO SURFACE INDICATION OF PIT

Type: Produced Water      Lined: NO      Pit ID:      Lat: 40.878523      Long: -103.365301

Reference Point: \_\_\_\_\_      Other: \_\_\_\_\_      Length: \_\_\_\_\_      Width: \_\_\_\_\_

**Lining:**

Liner Type: HDPE      Liner Condition: Adequate

Comment:

Corrective Action

Date: c

**Fencing:**

Fencing Type: Livestock      Fencing Condition: Adequate

Comment:

Corrective Action

Date:

**Netting:**

Netting Type: Mesh      Netting Condition: Good

Comment:

Corrective Action

Date:

Anchor Trench Present:      Oil Accumulation: NO      2+ feet Freeboard: YES

Comment:

Corrective Action

Date:

Type: Skimming/Settling      Lined: YES      Pit ID:      Lat:      Long:

Reference Point: \_\_\_\_\_      Other: \_\_\_\_\_      Length: \_\_\_\_\_      Width: \_\_\_\_\_

**Lining:**

Liner Type: HDPE      Liner Condition: Adequate

Comment:

Corrective Action

Date: c

**Fencing:**

Fencing Type: Livestock      Fencing Condition: Adequate

Comment:

Corrective Action

Date:

**Netting:**

Netting Type: Mesh      Netting Condition: Good

Comment:		Date:
Corrective Action		
Anchor Trench Present:	Oil Accumulation: <u>NO</u>	2+ feet Freeboard: <u>YES</u>
Comment:		Date:
Corrective Action		

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401285431	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4149176">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4149176</a>