

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/23/2017

Submitted Date:

05/24/2017

Document Number:

675103616**FIELD INSPECTION FORM**

Loc ID 335095 Inspector Name: GRANAHAH, KYLE On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 100185Name of Operator: ENCANA OIL & GAS (USA) INCAddress: 370 17TH ST STE 1700City: DENVER State: CO Zip: 80202-**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
☐ FOLLOW UP INSPECTION REQUIRED
☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:14 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
, Encana		cogcc.inspections@encana.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
271165	WELL	PR	10/09/2004	GW	045-09849	GMR 34-5CX (C34NW)	EG
271166	WELL	PR	10/12/2004	GW	045-09850	GMR 34-4D (C34W)	EG
271167	WELL	PR	10/05/2004	GW	045-09851	GMR 34-3D(C34NW)	EG
272842	WELL	PR	10/16/2004	GW	045-10170	GMR 33-1D(C34NW)	EG
279111	WELL	PR	10/11/2007	GW	045-10999	GMR 34-11A(C34NW)	EG
279112	WELL	PR	05/01/2010	GW	045-11000	GMR 34-5A (C34NW)	EG
279113	WELL	PR	10/07/2007	GW	045-11001	GMR 34-6D(C34NW)	EG

General Comment:

2017 Flowline NTO Inspection 1000' Buffer
 Facilities on location ID 335102 - All flowlines accounted for

LocationOverall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:	Present/complete		
Corrective Action:		Date:	
Type	BATTERY		
Comment:	Present/complete		
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 970-285-2615

Corrective Action:

Date: _____

Overall Good: ☒

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Fencing/:			
Type	LOCATION		
Comment:			
Corrective Action:		Date:	

Equipment:			corrective date
Type: Flow Line	#		
Comment:	7-3" steel lines from well to separators on location ID 335102		
Corrective Action:		Date:	
Type: Plunger Lift	# 7		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Chem tote with secondary containment		
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		

Corrective Action:		Date:	
--------------------	--	-------	--

Inspected Facilities									
Facility ID:	271165	Type:	WELL	API Number:	045-09849	Status:	PR	Insp. Status:	EG
Producing Well									
Comment:	Pr - via plunger lift , no leaks/venting - bradenhead monitored, remote pressure monitoring present								
Corrective Action:						Date:			
Facility ID:	271166	Type:	WELL	API Number:	045-09850	Status:	PR	Insp. Status:	EG
Producing Well									
Comment:	Pr - via plunger lift , no leaks/venting - bradenhead monitored, remote pressure monitoring present								
Corrective Action:						Date:			
Facility ID:	271167	Type:	WELL	API Number:	045-09851	Status:	PR	Insp. Status:	EG
Producing Well									
Comment:	Pr - via plunger lift , no leaks/venting - bradenhead monitored, remote pressure monitoring present								
Corrective Action:						Date:			
Facility ID:	272842	Type:	WELL	API Number:	045-10170	Status:	PR	Insp. Status:	EG
Producing Well									
Comment:	Pr - via plunger lift , no leaks/venting - bradenhead monitored, remote pressure monitoring present								
Corrective Action:						Date:			
Facility ID:	279111	Type:	WELL	API Number:	045-10999	Status:	PR	Insp. Status:	EG
Producing Well									
Comment:	Pr - via plunger lift , no leaks/venting - bradenhead monitored, remote pressure monitoring present								
Corrective Action:						Date:			
Facility ID:	279112	Type:	WELL	API Number:	045-11000	Status:	PR	Insp. Status:	EG
Producing Well									
Comment:	Pr - via plunger lift , no leaks/venting - bradenhead monitored, remote pressure monitoring present								
Corrective Action:						Date:			
Facility ID:	279113	Type:	WELL	API Number:	045-11001	Status:	PR	Insp. Status:	EG
Producing Well									
Comment:	Pr - via plunger lift , no leaks/venting - bradenhead monitored, remote pressure monitoring present								
Corrective Action:						Date:			

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Gravel	Pass			
Berms	Pass					
Ditches	Pass					
Gravel	Pass					
		Ditches	Pass			
Seeding	Pass					

Comment: [No sediment flow evident](#)

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
675103623	Flowline photo	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4155303