

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/19/2017

Submitted Date:

05/19/2017

Document Number:

673404639**FIELD INSPECTION FORM**

Loc ID 316760 Inspector Name: Waldron, Emily On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 9006Name of Operator: BOOCO'S CONTRACT SERVICES INCAddress: P O BOX 572City: HAYDEN State: CO Zip: 81639**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**9 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

| Contact Name | Phone | Email | Comment |
|--------------|-------|-------------------|----------------|
| Booco, Randy | | boocosinc@aol.com | owner operator |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 232679 | WELL | PR | 08/01/2013 | OW | 107-06093 | JONES 1-11 | PR |

General Comment:2017 Flowline NTO Inspection 1000' Buffer

LocationOverall Good: ☐

| | | | |
|----------------------|----------------------|-------|--|
| Signs/Marker: | | | |
| Type | TANK LABELS/PLACARDS | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type | WELLHEAD | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type | BATTERY | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Emergency Contact Number:

Comment: 970-276-3887

Corrective Action:

Date: _____

Overall Good: ☐

| | | | |
|--------------------|---|----------|------------------|
| Spills: | | | |
| Type | Area | Volume | |
| Lube Oil | Pump Jack | <= 1 bbl | |
| Comment: | Lube oil at side and rear of pump jack. | | |
| Corrective Action: | Control and contain spills/releases and clean up per Rule 906.a. Contact COGCC EPS staff. | | Date: 05/22/2017 |

In Containment: No

Comment:

☐ Multiple Spills and Releases?

| | | | |
|-----------------------------------|--|-------|-----------------|
| Equipment: | | | corrective date |
| Type: Flow Line | # | | |
| Comment: | IN USE: 1-2" steel riser and 1-1" steel riser 2-1" poly lines at wellhead. 40.48997, -107.11517 1-2" steel riser and 1-3" steel riser at separator. 40.49015, -107.11480 1-4" steel riser at manifold between separator and tank. 40.48996, -107.11476 1-4" steel riser 1-2" steel riser 1-3" steel riser at tank. 40.48987, -107.11468 2-4" steel risers at tank loadout/into tanks. 40.48760, -107.11615 1-4" steel riser at tank. 1-4" steel riser into tank 2 from wellhead location uphill. 40.48787, -107.11618 | | |
| Corrective Action: | | Date: | |
| Type: Deadman # & Marked | # 4 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Horizontal Heated Separator | # 1 | | |
| Comment: | 40.49015, -107.11480 | | |
| Corrective Action: | | Date: | |

| | | |
|-----------------------|---|-------|
| Type: Bird Protectors | # | |
| Comment: | | |
| Corrective Action: | | Date: |

Tanks and Berms:

| | | | | | |
|--------------------|--|----------|-----------|---------|-----------------------|
| Contents | # | Capacity | Type | Tank ID | SE GPS |
| CRUDE OIL | 1 | 400 BBLS | STEEL AST | | 40.489990,-107.114820 |
| Comment: | Stained soil at base. | | | | |
| Corrective Action: | Securely fasten all valves, pipes, and fittings to ensure good mechanical condition per Rule 605.d. Control and contain spills/releases and clean up per Rule 906.a. Contact COGCC EPS staff. | | | | Date: 05/15/2017 |

Paint

| | |
|------------------|----------|
| Condition | Adequate |
| Other (Content) | |
| Other (Capacity) | |
| Other (Type) | |

Berms

| | | | | | |
|--------------------|----------|---------------------|---------------------|-------------|-----------------------|
| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance | |
| Earth | Adequate | | | Adequate | |
| Comment: | | | | | |
| Corrective Action: | Date: | | | | |
| Contents | # | Capacity | Type | Tank ID | SE GPS |
| CRUDE OIL | 4 | 400 BBLS | STEEL AST | | 40.487820,-107.115890 |
| Comment: | | | | | |
| Corrective Action: | Date: | | | | |

Paint

| | |
|------------------|----------|
| Condition | Adequate |
| Other (Content) | |
| Other (Capacity) | |
| Other (Type) | |

Berms

| | | | | |
|--------------------|----------|---------------------|---------------------|-------------|
| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
| Earth | Adequate | | | Adequate |
| Comment: | | | | |
| Corrective Action: | Date: | | | |

Venting:

| | |
|--------------------|-------|
| Yes/No | NO |
| Comment: | |
| Corrective Action: | Date: |

Flaring:

| | |
|------|--|
| Type | |
|------|--|

| | | | |
|--------------------|--|-------|--|
| Comment: | | | |
| Corrective Action: | | Date: | |

| | | | | |
|-----------------------------|------------|-----------------------|------------|------------------|
| Inspected Facilities | | | | |
| Facility ID: 232679 | Type: WELL | API Number: 107-06093 | Status: PR | Insp. Status: PR |
| Producing Well | | | | |
| Comment: | Pumping. | | | |
| Corrective Action: | | | | Date: |

| |
|--|
| |
|--|

Reclamation - Storm Water - Pit**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| | | | | | | |

Comment: No apparent soil migration; erosion or soil movement.

Corrective Action:

Date:

Pits: ☐ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|----------------------|---|
| 401288421 | INSPECTION SUBMITTED | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4151892 |
| 673404640 | Inspection Photos | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4151891 |