

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/16/2017

Submitted Date:

05/19/2017

Document Number:

674603329**FIELD INSPECTION FORM**

Loc ID 428521 Inspector Name: Maclaren, Joe On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 8960Name of Operator: BONANZA CREEK ENERGY OPERATING COMPANYAddress: 410 17TH STREET SUITE #1400City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:3 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Chesson, Bob		robert.chesson@state.co.us	
,		EHSRC@bonanzacrk.com	
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
435423	WELL	PR	07/07/2014	OW	123-38606	Park T-P-4HC	EG

General Comment:

COGCC Integrity Inspection performed on May 16th, 2017 in response to initial form 19 spill report Doc #401278434 received on 05/12/2017 that outlines: During routine site inspections on 5/3/2017, an operator noted that a release occurred inside the separator cabinet at the Park T-4. It was discovered that the produced water dumpline was leaking. The release occurred beneath the secondary containment liner. After exposing the line and using a calibrated PID to remove all of the impacted soil the total release volume is estimated to be 19 bbls. Soil samples were taken and will be submitted for laboratory analysis. Once repaired, the line will be pressured tested prior to being put back in service. The details of observations made during this field inspection are available in the flowline section of this report. Photo's uploaded and can be accessed via link(s) at the end of this report.

LocationOverall Good: ☐

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good: ☐**Spills:**

Type

Area

Volume

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

corrective date

Type: Flow Line

#

Comment: Multiple unused flowline risers observed on this location; Must comply with requirements of COGCC NTO dated 5/2/2017 (as applicable).

Corrective Action:

Date:

Venting:

Yes/No

Comment:

Corrective Action:

Date:

Flaring:

Type

Comment:

Corrective Action:

Date:

Inspected Facilities

Facility ID: 435423 Type: WELL API Number: 123-38606 Status: PR Insp. Status: EG

Flowline

#1	Type: Dump Line	of Lines	
----	-----------------	----------	--

Flowline Description

Flowline Type: Dump Line Size: Material: Carbon Steel
 Variance: Age: Contents: Produced Water

Integrity Summary

Failures: Spills: Yes Repairs Made:
 Coatings: H2S: Cathodic Protection:

Pressure Testing

Witnessed: Test Result: Charted:

COGCC Rules(check all that apply)

☒ 1101. Installation and Reclamation ☒ 1102. Operations, Maintenance, and Repair ☐ 1103. Abandonment

Comment: Repairs are being completed on the produced water dump flowline(s) at the Park T-4 separator. The dump line is disconnected at this time. Excavation and remediation work observed in progress during this field inspection. Note: Document and retain records of root cause of failure evaluation, measures taken to prevent the problem from reoccurring and description of all flowline repairs completed (on supplemental form 19); perform flowline pressure testing to verify integrity of repairs completed (retain chart & data) prior to returning flowline to service.

Corrective Action:

Date:

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401287962	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4151342
674603334	Signage at Separators	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4151337
674603335	Remediation/ Dump line repairs in progress	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4151338
674603336	Disconnected unused flowline risers	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4151339
674603337	Disconnected unused risers at separators	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4151340