

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/19/2017

Submitted Date:

05/22/2017

Document Number:

674200075**FIELD INSPECTION FORM**

Loc ID 434375 Inspector Name: Gomez, Jason On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 10633Name of Operator: CRESTONE PEAK RESOURCES OPERATING LLCAddress: 1801 CALIFORNIA STREET #2500City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
☐ FOLLOW UP INSPECTION REQUIRED
☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:4 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
,		Cogcc.inspections@crestone pr.com	
Adamczyk, Megan		megan.adamczyk@state.co.u s	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
434370	WELL	DG	04/24/2017	LO	123-38122	Waste Connections 3A- 29H-M168	DG

General Comment:

LocationOverall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good: ☒**Spills:**

Type

Area

Volume

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

corrective date

Type:

#

Comment: 32' SOUND WALLS SURROUND LOCATION FOR SOUND MITIGATION

Corrective Action:

Date:

Venting:

Yes/No

Comment:

Corrective Action:

Date:

Flaring:

Type

Field Flare

Comment: NOT IN USE AT TIME OF INSPECTION

Corrective Action:

Date:

Inspected Facilities

Facility ID: 434370 Type: WELL API Number: 123-38122 Status: DG Insp. Status: DG

Complaint

Comment: Complaint Received May 19, 2017

Field Inspector Assigned: Jason E. Gomez

Complaint Received:

Date: 5-19-2017 Time 1000 Hrs

Contacted by Complaint Specialist per Complaint Response forms

Date: 5-19-2017

Well Number#: Location #: 434375

Inspection Document #: 674200075

Nature of complaint: Odor

Field Inspector Actions:

On 5-19-2017, I was contacted by complaint specialist Megan Adamczyk in reference to several complaints received by the COGCC about odor occurring in the Erie area south of the Crestone Peak Resources, Waste Connection drilling pad.

On 5-19-2017, I performed a complete site inspection of the Waste Connection location and the neighborhoods south and southeast of the drilling pad. At the time of inspection, I observed Ensign drilling rig 153 on the location performing drilling operation for Crestone Peak Resources. I reviewed location records, which did not show any abnormal drilling conditions at the time of the complaints.

As part of my inspection process I parked in the neighborhood at the end of Alpine Dr. and Crestview for approx. 2hrs. I did not detect any odors during this time.

All information reviewed and site inspection information were submitted to the complaint specialist for further review.

No violations of COGCC rules were observed at the time of the inspection.

Corrective Action:

Date:

Well Drilling

Rig: Rig Name: ENSIGN 153 Pusher/Rig Manager: PETER SANTOS

Permit Posted: Yes Access Sign: Yes

Well Control Equipment:

Pipe Ram: YES Blind Ram: YES Hydril Type: YES

Pressure Test BOP: Pass Test Pressure PSI: Safety Plan: YES

Drill Fluids Management:

Lined Pit: Unlined Pit: Closed Loop: YES Semi-Closed Loop:

Multi-Well: YES Disposal Location: WASTE CONNECTION

Comment:

Corrective Action:

Date:

Optical Gas Imaging SurveySurvey Type: ComplaintCurrent Operations: ☐ Production ☐ Workover ☐ Flowback ☐ Referred to APCD

GPS(entrance of location): Lat: _____ Long: _____

Wind: Gusts Speed: 5-10 (mph) Direction From: N Weather: Rain Temperature: 45 (F)

Assisting Staff: _____ Camera #: _____

☐ Visible Smoke ☐ Referred to CDPHE

Times Surveyed

Equipment Surveyed

Time Survey Start	AM/PM	Time Survey End	AM/PM	Equipment
				Other

Comment: Drilling Rig and Tanks

Corrective Action: _____ Date: _____

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401289941	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4153155
674200076	Thermal Imagery of Drilling Rig and Tanks	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4153153