

Inspection Photos - 2017 Flowline NTO
Inspection
Location Name: Govt-Winder 1
API: 05-081-05370



Photo 1. Wellhead with 1- 2" steel riser in use.



Photo 2. 1" steel flowline from wellhead to separator.

Inspection Photos - 2017 Flowline NTO
Inspection
Location Name: Govt-Winder 1
API: 05-081-05370



Photo 3. Lines going to separator and motor. Unlabeled methanol tank.



Photo 4. Location overview taken at entrance to location facing south.