

Inspection Photos - 2017 Flowline NTO
Inspection
Location Name: Brunner 1
API: 05-081-05368



Photo 1. Location overview taken at entrance to location facing south.



Photo 2. Overview of wellhead assembly with fallen wellhead sign and unlabeled methanol container visible.

Inspection Photos - 2017 Flowline NTO
Inspection
Location Name: Brunner 1
API: 05-081-05368



Photo 3. Stained soil at wellhead.



Photo 4. Wellhead assembly with 1 -2" steel riser in use, methanol lines, 1 - 1" steel riser not in use.

Inspection Photos - 2017 Flowline NTO
Inspection
Location Name: Brunner 1
API: 05-081-05368



Photo 5. 1 -1" steel riser not in use, alternate angle.



Photo 6. Lines connecting separator and motor.