

Inspection Photos - 2017 Flowline NTO
Inspection
Location Name: W W McWilliams 1-29
API: 05-081-05377



Photo 1. Location overview taken at entrance to location facing northeast.



Photo 2. Overview of wellhead assembly.

Inspection Photos - 2017 Flowline NTO
Inspection
Location Name: W W McWilliams 1-29
API: 05-081-05377



Photo 3. 1 -1" steel riser not in use at wellhead.



Photo 4. Unlabeled methanol tank.

Inspection Photos - 2017 Flowline NTO
Inspection
Location Name: W W McWilliams 1-29
API: 05-081-05377



Photo 5. 1' steel line running to separator.



Photo 6. 1 – 1" steel line to separator and 1 1" poly line to motor.