



**Location**

<b>Lease Road:</b>			
	Type	Access	
	comment:	Access is farmed over	
Corrective Action:			Date:

Overall Good:

<b>Signs/Marker:</b>			
	Type	WELLHEAD	
	Comment:	Lease sign by unit	
Corrective Action:			Date:

<b>Emergency Contact Number:</b>			
	Comment:		
	Corrective Action:		Date: _____

Overall Good:

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment: \_\_\_\_\_

Multiple Spills and Releases?

<b>Fencing/:</b>			
	Type	PUMP JACK	
	Comment:	Metal panels around unit and wellhead	
Corrective Action:			Date:

<b>Equipment:</b>					corrective date
Type:	Ancillary equipment	# 1			
	Comment:	Electric panel			
Corrective Action:				Date:	
Type:	Pump Jack	# 1			
	Comment:	Jensen unit			
Corrective Action:				Date:	
Type:	Prime Mover	# 1			
	Comment:	Electric motor			
Corrective Action:				Date:	

<b>Venting:</b>			
	Yes/No	NO	
	Comment:		
Corrective Action:			Date:

<b>Flaring:</b>			
Type			

Comment:	
Corrective Action:	Date:

**Inspected Facilities**

Facility ID: 253463 Type: WELL API Number: 125-07340 Status: PR Insp. Status: PR

**Producing Well**

Comment: [Producing. Casing production. Central meter run for \(KELLER 10-13, 19-13, 20-13\) 1200' SE @ KELLER 10-13 @ 39.87789/-102.47819](#)

Corrective Action:

Date:

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Other	Pass	Other	Pass			

Comment: [Location and access are farmed over](#)

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401292245	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4154933">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4154933</a>