

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/30/2017

Submitted Date:

05/31/2017

Document Number:

673404664**FIELD INSPECTION FORM**Loc ID 312968 Inspector Name: Waldron, Emily On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**OGCC Operator Number: 10407Name of Operator: ANTLER ENERGY LLCAddress: PO BOX 104City: BAGGS State: WY Zip: 82321**Findings:**15 Number of Comments4 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Neidel, Kris		kris.neidel@state.co.us	
Evans, Clay		antlerenergy@yahoo.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
223072	WELL	PR	08/26/1981	GW	081-06434	POWDER WASH FEDERAL 28-3	SI

**General Comment:**2017 Flowline NTO Inspection Statewide

**Location**Overall Good: ☒

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	Sign not posted or information inaccurate at well(s) or battery. No wellhead sign.		
Corrective Action:	Install sign to comply with Rule 210.b.	Date:	02/27/2015
Type	CONTAINERS		
Comment:	Sign not posted or information inaccurate on tanks or containers. No label on methanol container.		
Corrective Action:	Install sign to comply with Rule 210.d.	Date:	06/30/2017
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 307-380-7616

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☐

<b>Spills:</b>				
Type	Area	Volume		

In Containment: No

Comment: \_\_\_\_\_

☐ Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	OTHER		
Comment:	Landfarm fenced at 40.88992, -108.29888		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Flow Line	#		

Comment:	IN USE: at wellhead: 2 - 2" steel riser 2 - 1" steel riser 3 - 1" steel riser 1 - 1" steel riser to flowline to motor separator 1 - 1" poly flowline from separator to motor at meter run: 2 - 2" steel risers at horizontal separators: 6 - 2" steel risers 3 - 2" steel risers 2 - 1" steel risers at vertical separator: 3 - 2" steel risers at tank battery: 4 - 1" steel riser 2 - 2" steel insulated riser 1 - 1" steel risers 1 - 2" steel insulated riser 2 - 1" steel insulated riser 3 - 2" steel insulated riser				
Corrective Action:				Date:	
Type: Flow Line	#				
Comment:	NOT IN USE: at tank battery: 4 - 2" steel riser 1 - 3" steel riser at separators: 1 - 2" steel riser				
Corrective Action:				Date:	
Type: Vertical Heated Separator	# 1				
Comment:	40.88956, -108.29929				
Corrective Action:				Date:	
Type: Bird Protectors	#				
Comment:					
Corrective Action:				Date:	
Type: Gas Meter Run	# 1				
Comment:	40.88977, -108.29858				
Corrective Action:				Date:	
Type: Deadman # & Marked	# 4				
Comment:					
Corrective Action:				Date:	
Type: Horizontal Heated Separator	# 2				
Comment:	40.88956, -108.29929				
Corrective Action:				Date:	
Type: Pump Jack	# 1				
Comment:					
Corrective Action:				Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	4	400 BBLS	HEATED STEEL AST		40.889610,-108.298660
Comment:					
Corrective Action:					Date:
<b>Paint</b>					
Condition	Adequate				

Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate			Adequate
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:			Date:

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	223072	Type:	WELL	API Number:	081-06434	Status:	PR	Insp. Status:	SI
Idle Well									
Purpose: <input checked="" type="checkbox"/> Shut In <input type="checkbox"/> Temporarily Abandoned      Reminder: _____									
Comment: <input type="text" value="Not pumping."/> _____									
Corrective Action: <input type="text"/> _____      Date: _____									

## Reclamation - Storm Water - Pit

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: No apparent soil migration; erosion or soil movement.

Corrective Action:

Date: \_\_\_\_\_

**Pits:** ☐ NO SURFACE INDICATION OF PIT

Type: \_\_\_\_\_ Lined: \_\_\_\_\_ Pit ID: \_\_\_\_\_ Lat: 40.889770 Long: -108.299390

Reference Point: \_\_\_\_\_ Other: \_\_\_\_\_ Length: \_\_\_\_\_ Width: \_\_\_\_\_

**Lining:**

Liner Type: \_\_\_\_\_ Liner Condition: \_\_\_\_\_

Comment:

Corrective Action

Date: c**Fencing:**

Fencing Type: Livestock Fencing Condition: Adequate

Comment:

Corrective Action

Date: \_\_\_\_\_

**Netting:**

Netting Type: \_\_\_\_\_ Netting Condition: \_\_\_\_\_

Comment:

Corrective Action

Date: \_\_\_\_\_

Anchor Trench Present: \_\_\_\_\_ Oil Accumulation: \_\_\_\_\_ 2+ feet Freeboard: \_\_\_\_\_

Comment: Two pit ids with this location 100421, 100424 neither associated with Antler as operator.

Corrective Action

Date: 11/24/2016

Please work with COGCC environmental staff Kris Neidel kris.neidel@state.co.us 970-871-1963 to identify which pit ID is appropriate, proper pit operation, and to close pit if not in use.

Type: \_\_\_\_\_ Lined: \_\_\_\_\_ Pit ID: \_\_\_\_\_ Lat: 40.889570 Long: -108.298610

Reference Point: \_\_\_\_\_ Other: \_\_\_\_\_ Length: \_\_\_\_\_ Width: \_\_\_\_\_

**Lining:**

Liner Type: \_\_\_\_\_ Liner Condition: \_\_\_\_\_

Comment:

Corrective Action

Date: c**Fencing:**

Fencing Type: \_\_\_\_\_ Fencing Condition: \_\_\_\_\_

Comment:

Corrective Action

Date: \_\_\_\_\_

**Netting:**

Netting Type: Mesh Netting Condition: Sagging into pit contents

Inspector Name: Waldron, Emily

Comment:		Date:
Corrective Action		
Anchor Trench Present:	Oil Accumulation:	2+ feet Freeboard:
Comment:	Two pit ids with this location 100421, 100424 neither associated with Antler as operator.	
Corrective Action	Please work with COGCC environmental staff Kris Neidel kris.neidel@state.co.us 970-871-1963 to identify which pit ID is appropriate, proper pit operation, and to close pit if not in use.	
		Date: 11/24/2016

**COGCC Comments**

Comment	User	Date
Follow up to inspection from 10/12/2016 document number 673403735. Several corrective actions remain outstanding.	waldrone	05/31/2017

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
673404668	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4158966">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4158966</a>