

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/30/2017

Submitted Date:

05/31/2017

Document Number:

673404665

**FIELD INSPECTION FORM**

Loc ID 312995 Inspector Name: Waldron, Emily On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 10407  
Name of Operator: ANTLER ENERGY LLC  
Address: PO BOX 104  
City: BAGGS State: WY Zip: 82321

**Findings:**

- 13 Number of Comments
- 3 Number of Corrective Actions
- Corrective Action Response Requested

**Contact Information:**

Contact Name	Phone	Email	Comment
Neidel, Kris		kris.neidel@state.co.us	
Evans, Clay		antlerenergy@yahoo.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
223241	WELL	PR	11/15/1985	OW	081-06605	POWDER WASH FEDERAL 28-7	SI

**General Comment:**

[2017 Flowline NTO Inspection Statewide](#)

**Location**

Overall Good:

<b>Signs/Marker:</b>			
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:	Sign not posted or information inaccurate on tanks or containers. Unlabeled container at wellhead and meter run.		
Corrective Action:	Install sign to comply with Rule 210.d.	Date:	06/30/2017
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

<b>Emergency Contact Number:</b>			
Comment:	307-380-7616		
Corrective Action:			Date: _____

Overall Good:

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

<b>Equipment:</b>			corrective date
Type: Vertical Heated Separator	# 1		
Comment:	40.88589, -108.29387		
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 1		
Comment:	40.88580, -108.29441		
Corrective Action:		Date:	
Type: Vertical Heated Separator	# 1		
Comment:	40.88580, -108.29441		
Corrective Action:		Date:	
Type: Flow Line	#		

Comment:	IN USE: at wellhead: 2 - 2" steel riser 3 - 1" steel riser at stand alone vertical separator: 1 - 2" steel riser at eastern horizontal separator: 5 - 2" steel riser and 1 - 1" steel riser at middle horizontal separator: 3 - 1" steel riser and 1 - 2" steel riser at vertical separator: 3 - 2" steel risers at tank battery: 2 - 1" steel riser 1 - 2" steel riser 3 - 1" steel riser at meter run: 2 -2" steel risers			Date:
Corrective Action:				Date:
Type: Deadman # & Marked	# 4			
Comment:				Date:
Corrective Action:				Date:
Type: Gas Meter Run	# 1			
Comment:				Date:
Corrective Action:				Date:
Type: Flow Line	#			
Comment:	NOT IN USE: 1 - 2" steel riser at 40.88615, -108.29376 3 - 2" steel risers at 40.88588, -108.29424			Date:
Corrective Action:				Date:
Type: Bird Protectors	#			
Comment:				Date:
Corrective Action:				Date:
Type: Pump Jack	# 1			
Comment:	Stained soil at wellhead.			Date:
Corrective Action:	Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.			Date: 06/30/2017

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	2	400 BBLs	HEATED STEEL AST		40.885890,-108.294570
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate			Adequate
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 223241 Type: WELL API Number: 081-06605 Status: PR Insp. Status: SI

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment:

Corrective Action:  Date: \_\_\_\_\_

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: No apparent soil migration; erosion or soil movement.

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

Type:	Lined:	Pit ID:	Lat:	Long:
-------	--------	---------	------	-------

Reference Point: \_\_\_\_\_ Other: \_\_\_\_\_ Length: \_\_\_\_\_ Width: \_\_\_\_\_

**Lining:**

Liner Type: \_\_\_\_\_ Liner Condition: \_\_\_\_\_

Comment:

Corrective Action

Date:   

**Fencing:**

Fencing Type: \_\_\_\_\_ Fencing Condition: \_\_\_\_\_

Comment:

Corrective Action

Date: \_\_\_\_\_

**Netting:**

Netting Type: \_\_\_\_\_ Netting Condition: \_\_\_\_\_

Comment:

Corrective Action

Date: \_\_\_\_\_

Anchor Trench Present: \_\_\_\_\_ Oil Accumulation: \_\_\_\_\_ 2+ feet Freeboard: \_\_\_\_\_

Comment: Pit in tank battery. Two pit id's associated with this location. 100422 and 100425, neither permitted to Antler Energy.

Corrective Action

Please work with COGCC environmental staff Kris Neidel kris.neidel@state.co.us 970-871-1963 to identify which pit ID is appropriate, proper pit operation, and to close pit if not in use.

Date: 11/12/2016

**COGCC Comments**

Comment	User	Date
<span style="color: blue;">Follow up to inspection from 10/12/2016 document number 673403734. Corrective actions remain outstanding.</span>	waldrone	05/31/2017

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
673404669	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4158967">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4158967</a>