

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/27/2017

Submitted Date:

05/31/2017

Document Number:

681902226**FIELD INSPECTION FORM**Loc ID 321459 Inspector Name: HELGELAND, GARY On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10633Name of Operator: CRESTONE PEAK RESOURCES OPERATING LLCAddress: 1801 CALIFORNIA STREET #2500City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:11 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
,		Cogcc.inspections@crestone pr.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
272632	WELL	PR	07/07/2005	OW	013-06509	VICKLUND G 32-2	PR

General Comment:[2017 Flowline NTO Inspection 1000' Buffer. Shadowing Operator Pressure Testing Team.](#)

LocationOverall Good: ☒**Signs/Marker:**

Type	WELLHEAD		
Comment:	SATISFACTORY		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	SATISFACTORY	Date:	
Corrective Action:			

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Fencing/:**

Type	WELLHEAD		
Comment:	Barbed wire topped chain link		
Corrective Action:		Date:	

Equipment:

Type: Plunger Lift	# 1		corrective date
Comment:	Refer to inspection # 681902224 for information concerning shared battery and equipment.		
Corrective Action:		Date:	
Type: Flow Line	#		
Comment:	1-2" steel riser at well.		
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
Comment:	Refer to inspection # 681902224 for information concerning shared battery and equipment.				
Corrective Action:		Date:			

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
------	----------	---------------------	---------------------	-------------

Inspected FacilitiesFacility ID: 272632 Type: WELL API Number: 013-06509 Status: PR Insp. Status: PR**Producing Well**Comment: PR

Corrective Action:

Date:

BradenHeadComment: Bradenhead is plumed to surface.

Corrective Action:

Date:

Flowline

#1

Type: Well Site

of Lines

Flowline DescriptionFlowline Type: Well SiteSize: 2"Material: Carbon Steel

Variance:

Age:

Contents: Multiphase**Integrity Summary**

Failures:

Spills:

Repairs Made:

Coatings:

H2S:

Cathodic Protection:

Pressure TestingWitnessed: YesTest Result: PassCharted: Yes**COGCC Rules(check all that apply)**☐ 1101. Installation and Reclamation☒ 1102. Operations, Maintenance, and Repair☐ 1103. AbandonmentComment: Refer to inspection # 681902224 for chart of flowline test.

Corrective Action:

Date:

Environmental**Spill/Remediation:**Comment: Corrective
Action: Date: Emission Control Burner (ECB): YESComment: Pilot: OFFWildlife Protection Devices (fired vessels): YES**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
681902227	well	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4159710