

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/24/2017

Submitted Date:

05/25/2017

Document Number:

667601623**FIELD INSPECTION FORM**
 Loc ID 320368 Inspector Name: Kraich, Adam On-Site Inspection ☐ 2A Doc Num:                     
**Operator Information:**OGCC Operator Number: 47120Name of Operator: KERR MCGEE OIL & GAS ONSHORE LPAddress: P O BOX 173779City: DENVER State: CO Zip: 80217-**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**13 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
,		cogccinspections@anadarko.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
203559	WELL	PR	03/23/1995	GW	001-09119	SELTZER 23-3	PR

**General Comment:**

**Location**Overall Good: ☒

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Adequate		
Corrective Action:		Date:	
Type	BATTERY		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment: Adequate

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☒

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	TANK BATTERY		
Comment:	4 strand barbed wire		
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	4 strand barbed wire		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Rod iron		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Plunger Lift	# 1		
Comment:	automated valve control		
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 1		

Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 1		
Comment:	separator exhaust		
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	100 BBLs	PBV FIBERGLASS		,
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:	shares berm with production tank.			
Corrective Action:				Date:

**Venting:**

Yes/No		
--------	--	--

Comment:			
Corrective Action:		Date:	
<b>Flaring:</b>			
Type			
Comment:			
Corrective Action:		Date:	

--	--	--	--

**Inspected Facilities**

Facility ID: 203559 Type: WELL API Number: 001-09119 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR, SI for flow line NTO

Corrective Action:

Date:

**Flowline**

#1 Type: Process Piping

of Lines

**Flowline Description**

Flowline Type: Process Piping

Size: Other

Material: Poly

Variance:

Age:

Contents: Natural Gas

**Integrity Summary**

Failures:

Spills:

Repairs Made:

Coatings:

H2S:

Cathodic Protection:

**Pressure Testing**

Witnessed:

Test Result:

Charted:

**COGCC Rules(check all that apply)**

☐ 1101. Installation and Reclamation

☐ 1102. Operations, Maintenance, and Repair

☒ 1103. Abandonment

Comment: 1" poly supply line, is locked out tagged out and painted per flow line NTO issued in may.

Corrective Action:

Date:

**COGCC Comments**

Comment

User

Date

Well head and separator have 1" poly supply line, it is locked out tagged out and painted on each ends.

kraicha

05/25/2017

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401293688	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4156316">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4156316</a>
667601624	Inspection photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4156308">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4156308</a>