

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/25/2017

Submitted Date:

05/25/2017

Document Number:

675103631

FIELD INSPECTION FORM

Loc ID 335359 Inspector Name: GRANAHAN, KYLE On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 100185
Name of Operator: ENCANA OIL & GAS (USA) INC
Address: 370 17TH ST STE 1700
City: DENVER State: CO Zip: 80202-

Findings:

17 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
, Encana		cogcc.inspections@encana.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
257648	WELL	PR	10/13/2004	GW	045-07583	KELL 35-3	EG
257649	WELL	PR	04/12/2001	GW	045-07584	GMU 26-14 (C35)	EG
257660	WELL	PR	10/13/2004	GW	045-07585	BENZEL 35-7 (C35)	EG
257665	WELL	PR	10/13/2004	GW	045-07589	KELL 35-6 (C35)	EG
273777	WELL	PR	03/05/2005	GW	045-10283	CRAIG 35-6A (C35)	EG
273779	WELL	PR	03/04/2005	GW	045-10284	CRAIG 35-5A (C35)	EG
274937	WELL	PR	03/22/2005	GW	045-13440	GMU 35-4A1(C35)	EG

General Comment:

[2017 Flowline NTO inspection 1000' buffer](#)

Location

Overall Good:

Signs/Marker:

Type	TANK LABELS/PLACARDS		
Comment:	Present/complete		
Corrective Action:			Date:
Type	BATTERY		
Comment:	Present/complete		
Corrective Action:			Date:
Type	WELLHEAD		
Comment:	Present/complete		
Corrective Action:			Date:

Emergency Contact Number:

Comment:

Corrective Action:

Date:

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

Type				corrective date
Type: Bird Protectors	# 5			
Comment:				
Corrective Action:				Date:
Type: Horizontal Heated Separator	# 4			
Comment:	Center of separator bank 39.48840/-107.74483			
Corrective Action:				Date:
Type: Vertical Heated Separator	# 3			
Comment:				
Corrective Action:				Date:
Type: Flow Line	#			
Comment:	Not In Use - 3 - 1" steel dump lines from separator - tied into main dump line/identified and psi tested.			
Corrective Action:				Date:
Type: Flow Line	#			
Comment:	IN USE; 3-3" steel risers from wells to separators. 4-2" steel risers from wells to separators. 3-3" steel risers from gas out separator to sales line. 4-2" steel risers from gas out separator to sales line. 3-2" steel risers from separator water/oil dump to tank battery. 1 - 1" steel riser from separator water/oil dump to tank battery. 1-2" steel riser from separator gas out to gas meter sales. 2-3" steel risers from separator water/oil dump to tank battery.			

Corrective Action:		Date:	
Type: Plunger Lift	# 3		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:	39.48840/-107.74483		
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	300 BBLs	STEEL AST		
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	400 BBLs	STEEL AST		39.488410,-107.745220
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO	
Comment:		

Corrective Action:		Date:	
Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities									
Facility ID:	257648	Type:	WELL	API Number:	045-07583	Status:	PR	Insp. Status:	EG
Producing Well									
Comment:	PR - no leaks/venting - remote bradenhead and pressure monitoring present				Date:				
Corrective Action:					Date:				
Facility ID:	257649	Type:	WELL	API Number:	045-07584	Status:	PR	Insp. Status:	EG
Producing Well									
Comment:	PR - no leaks/venting - remote bradenhead and pressure monitoring present				Date:				
Corrective Action:					Date:				
Facility ID:	257660	Type:	WELL	API Number:	045-07585	Status:	PR	Insp. Status:	EG
Producing Well									
Comment:	PR - no leaks/venting - remote bradenhead and pressure monitoring present				Date:				
Corrective Action:					Date:				
Facility ID:	257665	Type:	WELL	API Number:	045-07589	Status:	PR	Insp. Status:	EG
Producing Well									
Comment:	PR - no leaks/venting - remote bradenhead and pressure monitoring present				Date:				
Corrective Action:					Date:				
Facility ID:	273777	Type:	WELL	API Number:	045-10283	Status:	PR	Insp. Status:	EG
Producing Well									
Comment:	PR - via plunger lift, no leaks/venting - remote bradenhead and pressure monitoring present				Date:				
Corrective Action:					Date:				
Facility ID:	273779	Type:	WELL	API Number:	045-10284	Status:	PR	Insp. Status:	EG
Producing Well									
Comment:	PR - via plunger lift, no leaks/venting - remote bradenhead and pressure monitoring present				Date:				
Corrective Action:					Date:				
Facility ID:	274937	Type:	WELL	API Number:	045-13440	Status:	PR	Insp. Status:	EG
Producing Well									
Comment:	PR - via plunger lift, no leaks/venting - remote bradenhead and pressure monitoring present				Date:				
Corrective Action:					Date:				

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Ditches	Pass					
		Ditches	Pass			
Berms	Pass					
Gravel	Pass					
		Gravel	Pass			

Comment: [No sediment flow evident](#)

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401293856	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4156540
675103632	Flowline photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4156537