

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/31/2017

Submitted Date:

06/01/2017

Document Number:

675103649**FIELD INSPECTION FORM**

Loc ID 334347 Inspector Name: GRANAHAH, KYLE On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 100185Name of Operator: ENCANA OIL & GAS (USA) INCAddress: 370 17TH ST STE 1700City: DENVER State: CO Zip: 80202-**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
☐ FOLLOW UP INSPECTION REQUIRED
☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:14 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

| Contact Name | Phone | Email | Comment |
|--------------|-------|------------------------------|---------|
| , Encana | | cogcc.inspections@encana.com | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|--------------------|-------------|
| 284301 | WELL | PR | 02/01/2007 | GW | 077-09051 | RADEL 11-12 (OL11) | EG |
| 284302 | WELL | PR | 01/07/2008 | GW | 077-09050 | RADEL 10-9 (OL11) | EG |
| 284303 | WELL | PR | 01/07/2008 | GW | 077-09049 | RADEL 10-16(OL11) | EG |

General Comment:2017 Flowline NTO inspection 1000' buffer

LocationOverall Good: ☒

| | | | |
|----------------------|----------------------|-------|--|
| Signs/Marker: | | | |
| Type | BATTERY | | |
| Comment: | Present/complete | | |
| Corrective Action: | | Date: | |
| Type | TANK LABELS/PLACARDS | | |
| Comment: | Present/complete | | |
| Corrective Action: | | Date: | |
| Type | WELLHEAD | | |
| Comment: | Present/complete | | |
| Corrective Action: | | Date: | |

Emergency Contact Number:

Comment: 970-625-4209

Corrective Action:

Date: _____

Overall Good: ☒

| | | | |
|----------------|------|--------|--|
| Spills: | | | |
| Type | Area | Volume | |

In Containment: No

Comment:

☐ Multiple Spills and Releases?

| | | | |
|-----------------------------------|--|-------|-----------------|
| Equipment: | | | corrective date |
| Type: Ancillary equipment | # 1 | | |
| Comment: | Chem tote with secondary containment | | |
| Corrective Action: | | Date: | |
| Type: Gas Meter Run | # 1 | | |
| Comment: | 39.36201/-108.08506 | | |
| Corrective Action: | | Date: | |
| Type: Bird Protectors | # 3 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Flow Line | # | | |
| Comment: | IN USE; 3-3" steel risers from wells to separators. 3-3" steel risers from gas out separator to sales line. 3-2" steel risers from separator water/oil dump to tank battery. 1 -3" steel riser from separator gas out to gas meter sales. 3-2" steel risers from separator water/oil dump to tank battery. | | |
| Corrective Action: | | Date: | |
| Type: Horizontal Heated Separator | # 3 | | |
| Comment: | 39.36201/-108.08506 | | |
| Corrective Action: | | Date: | |

Tanks and Berms:

| | | | | | | |
|--------------------|---|----------|-----------|---------|-----------------------|--|
| Contents | # | Capacity | Type | Tank ID | SE GPS | |
| CONDENSATE | 2 | 300 BBLs | STEEL AST | | 39.361960,-108.085410 | |
| Comment: | | | | | | |
| Corrective Action: | | | | | Date: | |

Paint

| | | |
|------------------|----------|--|
| Condition | Adequate | |
| Other (Content) | | |
| Other (Capacity) | | |
| Other (Type) | | |

Berms

| | | | | | |
|--------------------|----------|---------------------|---------------------|-------------|-------|
| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance | |
| Metal | Adequate | Walls Sufficient | Base Sufficient | Adequate | |
| Comment: | | | | | |
| Corrective Action: | | | | | Date: |

Venting:

| | | | |
|--------------------|----|--|-------|
| Yes/No | NO | | |
| Comment: | | | |
| Corrective Action: | | | Date: |

Flaring:

| | | |
|--------------------|--|-------|
| Type | | |
| Comment: | | |
| Corrective Action: | | Date: |

Inspected Facilities

Facility ID: 284301 Type: WELL API Number: 077-09051 Status: PR Insp. Status: EG

Idle WellPurpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: EQUIPMENT ONSITE

Comment: Well SI at time of inspection, bradenhead/well pressure remotely monitored

Corrective Action: Date:

Flowline

#1 Type: Well Site of Lines

Flowline Description

Flowline Type: Well Site Size: Material:

Variance: Age: Contents:

Integrity Summary

Failures: Spills: Repairs Made:

Coatings: H2S: Cathodic Protection:

Pressure Testing

Witnessed: Test Result: Charted:

COGCC Rules(check all that apply)☐ 1101. Installation and Reclamation ☒ 1102. Operations, Maintenance, and Repair ☐ 1103. Abandonment

Comment: IN USE; 3-3" steel risers from wells to separators. 3-3" steel risers from gas out separator to sales line. 3-2" steel risers from separator water/oil dump to tank battery. 1-3" steel riser from separator gas out to gas meter sales. 3-2" steel risers from separator water/oil dump to tank battery.

Corrective Action: Date:

Facility ID: 284302 Type: WELL API Number: 077-09050 Status: PR Insp. Status: EG

Idle WellPurpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: EQUIPMENT ONSITE

Comment: Well SI at time of inspection, bradenhead/well pressure remotely monitored

Corrective Action: Date:

Facility ID: 284303 Type: WELL API Number: 077-09049 Status: PR Insp. Status: EG

Idle WellPurpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: EQUIPMENT ONSITE

Comment: Well SI at time of inspection, bradenhead/well pressure remotely monitored

Corrective Action: Date:

Reclamation - Storm Water - Pit**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Retention Ponds | Pass | | | | | |
| Gravel | Pass | | | | | |
| Berms | Pass | | | | | |
| Compaction | Pass | | | | | |

Comment: [No sediment flow evident](#)

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|---------------------|---|
| 675103652 | flow line photo log | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4160321 |