

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/01/2017

Submitted Date:

06/05/2017

Document Number:

674603355**FIELD INSPECTION FORM**

Loc ID 327486 Inspector Name: Maclaren, Joe On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 47120Name of Operator: KERR MCGEE OIL & GAS ONSHORE LPAddress: P O BOX 173779City: DENVER State: CO Zip: 80217-**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
☐ FOLLOW UP INSPECTION REQUIRED
☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:4 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

| Contact Name | Phone | Email | Comment |
|--------------------|-------|-------------------------------|---------|
| Gintautas, Peter | | peter.gintautas@state.co.us | |
| Schlagenhauf, Mark | | mark.schlagenhauf@state.co.us | |
| , | | cogccinspections@anadarko.com | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------------|-------------|
| 246961 | WELL | PR | 02/21/2004 | GW | 123-14758 | BERIG UPRR 41-35 #2 | EG |

General Comment:

COGCC Integrity Inspection performed on June 1st, 2017 in response to initial form 19 spill report Doc #401293024 received on 05/26/2017 that outlines: On May 23, 2017, historical impacts were discovered during P&A activities at the Berig UPRR 42-35 #1 production facility. Site infrastructure has been removed and will not be replaced. The details of observations made during this field inspection are available in the equipment and comment sections of this report. Photo's uploaded and can be accessed via link(s) at the end of this report.

LocationOverall Good: ☐

Emergency Contact Number:

Comment: Corrective Action: Date: Overall Good: ☐**Spills:**

| Type | Area | Volume | | |
|------|------|--------|--|--|
|------|------|--------|--|--|

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Equipment:**

corrective date

Type: Gas Meter Run

1

Comment: Remove unused equipment from (P/A) location.

Corrective Action: Date:

Type: Flow Line

1

Comment: NOT IN USE: Natural gas flowline (and riser) entering meter run housing on the NE side of facility pad. Note: Properly abandon flowlines (and remove associated risers) according to COGCC rule 1103.

Corrective Action: Date: **Venting:**

Yes/No

Comment: Corrective Action: Date: **Flaring:**

Type

Comment: Corrective Action: Date:

Inspected Facilities

Facility ID: 246961 Type: WELL API Number: 123-14758 Status: PR Insp. Status: EG

COGCC Comments

| Comment | User | Date |
|--|----------|------------|
| Well has been plugged and abandoned. Abandonment of facility and remediation activities are in progress. | maclarej | 06/05/2017 |

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|---------------------------------------|---|
| 674603359 | Out of service flowline and meter run | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4162318 |
| 674603361 | View of facility pad (looking west) | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4162319 |