



**photo 1:** Facing northeast toward the location. The location has been built and has not been reclaimed.



**photo 2:** Facing north along the topsoil pile at the west side of the location. There are weed issues and signs of erosion occurring along the topsoil pile.



**photo 3:** There is a marker at the center of the location and there is no signs of drilling at the location.



**photo 4:** There is a pit at the east side of the location which has torn liner debris.



**photo 5:** Facing south at the east side of the location toward the pit.



**photo 6:** A second pit remains open at the northeast side of the location.



**photo 7:** East side of the location facing southwest.



**photo 8:** Facing south along the east fill slope. There are signs of erosion occurring around the location.



**photo 9:** Northeast corner of the location facing southeast.



**photo 10:** Facing west at the surrounding undisturbed reference area.