

FORM  
INSPRev  
X/15

## State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/30/2017

Submitted Date:

05/30/2017

Document Number:

666803191

### FIELD INSPECTION FORM

Loc ID 335078 Inspector Name: Murray, Richard On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION  
 FOLLOW UP INSPECTION REQUIRED  
 NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 10531  
 Name of Operator: VANGUARD OPERATING LLC  
 Address: 5847 SAN FELIPE #3000  
 City: HOUSTON State: TX Zip: 77057

**Findings:**

13 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**Contact Information:**

Contact Name	Phone	Email	Comment
Ghan, Scott		sghan@vnrlc.com	<a href="#">Sr. EH&amp;S</a>
Axelson, Aaron	970-230-0926	aaxelson@vnrlc.com	<a href="#">Sr. Production Foreman</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
211294	WELL	PR	09/12/1996	GW	045-07053	PORTER FEDERAL 14-28-6-92	PR
279923	WELL	PR	08/16/2006	GW	045-11108	SPECIALTY FEDERAL 24D-28-692	PR
279924	WELL	PR	08/17/2006	GW	045-11109	SPECIALTY FEDERAL 24C-28-692	PR
279925	WELL	PR	08/09/2006	GW	045-11110	SPECIALTY FEDERAL 23A-28-692	PR

**General Comment:**

[2017 Flowline NTO Inspection 1000' Buffer Shadowing Operator Pressure Testing Team](#)

**Location**

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good:

**Spills:**

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

**Equipment:**

Type	#	Comment	Corrective Action	Date	corrective date
Emission Control Device	# 1	39.492500/-107.674600			
Plunger Lift	# 4	39.492754/-107.674230			
Horizontal Heated Separator	# 4	39.492486/-107.674402			

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	200 BBLs	STEEL AST		
Comment: In same berm as 3-300 bbls condensate					
Corrective Action:					Date:

**Paint**

Condition Adequate

Other (Content)

Other (Capacity)

Other (Type)

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
METHANOL	1	OTHER	STEEL AST		39.500880,-107.674616
Comment: <input type="text"/>					

Corrective Action:						Date:	
<u>Paint</u>							
Condition	Adequate						
Other (Content)							
Other (Capacity)	500gal						
Other (Type)							
<u>Berms</u>							
Type	Capacity		Permeability (Wall)		Permeability (Base)		Maintenance
Metal	Adequate		Walls Sufficent		Base Sufficent		Adequate
Comment:							
Corrective Action:						Date:	
Contents	#	Capacity	Type		Tank ID	SE GPS	
OTHER	1	200 BBLs	STEEL AST			39.493943,-107.674343	
Comment:							
Corrective Action:						Date:	
<u>Paint</u>							
Condition							
Other (Content) separator sand							
Other (Capacity)							
Other (Type)							
<u>Berms</u>							
Type	Capacity		Permeability (Wall)		Permeability (Base)		Maintenance
Earth	Adequate		Walls Sufficent		Base Sufficent		Adequate
Comment:							
Corrective Action:						Date:	
Contents	#	Capacity	Type		Tank ID	SE GPS	
CONDENSATE	3	300 BBLs	STEEL AST			39.492486,-107.674554	
Comment:							
Corrective Action:						Date:	
<u>Paint</u>							
Condition	Adequate						
Other (Content)							
Other (Capacity)							
Other (Type)							
<u>Berms</u>							
Type	Capacity		Permeability (Wall)		Permeability (Base)		Maintenance
Metal	Adequate		Walls Sufficent		Base Sufficent		Adequate
Comment:							
Corrective Action:						Date:	
Contents	#	Capacity	Type		Tank ID	SE GPS	

CONDENSATE	4	500 BBLs	STEEL AST		39.492920,-107.674606	
Comment:						
Corrective Action:					Date:	
<b>Paint</b>						
Condition	Adequate					
Other (Content)						
Other (Capacity)						
Other (Type)						
<b>Berms</b>						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate		
Comment:						
Corrective Action:					Date:	
<b>Venting:</b>						
Yes/No	YES					
Comment:	Bradenhead valves open					
Corrective Action:					Date:	
<b>Flaring:</b>						
Type						
Comment:						
Corrective Action:					Date:	

**Inspected Facilities**

Facility ID: 211294 Type: WELL API Number: 045-07053 Status: PR Insp. Status: PR

**Producing Well**

Comment: Plunger lift

Corrective Action:

Date:

**Flowline**

#1 Type: Well Site

4 of Lines

Flowline Description

Flowline Type: Well Site

Size: 2"

Material: Carbon Steel

Variance:

Age:

Contents: Natural Gas

Integrity Summary

Failures:

Spills:

Repairs Made:

Coatings:

H2S:

Cathodic Protection:

Pressure Testing

Witnessed: Yes

Test Result: Pass

Charted: Yes

COGCC Rules(check all that apply)

1101. Installation and Reclamation

1102. Operations, Maintenance, and Repair

1103. Abandonment

Comment:

Corrective Action:

Date:

#2 Type: Dump Line

2 of Lines

Flowline Description

Flowline Type: Dump Line

Size: 3"

Material: Carbon Steel

Variance:

Age:

Contents:

Integrity Summary

Failures:

Spills:

Repairs Made:

Coatings:

H2S:

Cathodic Protection:

Pressure Testing

Witnessed: Yes

Test Result: Pass

Charted: Yes

COGCC Rules(check all that apply)

1101. Installation and Reclamation

1102. Operations, Maintenance, and Repair

1103. Abandonment

Comment:

Corrective Action:

Date:

#3 Type: Process Piping

1 of Lines

Flowline Description

Flowline Type: Process Piping

Size: Other

Material: Carbon Steel

Variance:

Age:

Contents: Natural Gas

Integrity Summary

Failures:

Spills:

Repairs Made:

Coatings:

H2S:

Cathodic Protection:

Pressure Testing

Witnessed: Yes

Test Result: Pass

Charted: Yes

COGCC Rules(check all that apply)

1101. Installation and Reclamation

1102. Operations, Maintenance, and Repair

1103. Abandonment

Comment: Supply line to ECB

Corrective Action:

Date:

#4	Type:Sales Line	1 of Lines
----	-----------------	------------

Flowline Description

Flowline Type: Sales Line

Size: 3"

Material: Carbon Steel

Variance:

Age:

Contents: Natural Gas

Integrity Summary

Failures:

Spills:

Repairs Made:

Coatings:

H2S:

Cathodic Protection:

Pressure Testing

Witnessed: Yes

Test Result: Pass

Charted: Yes

COGCC Rules(check all that apply)

1101. Installation and Reclamation

1102. Operations, Maintenance, and Repair

1103. Abandonment

Comment:

Corrective Action:

Date:

Facility ID: <u>279923</u>	Type: <u>WELL</u>	API Number: <u>045-11108</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
----------------------------	-------------------	------------------------------	-------------------	-------------------------

**Producing Well**

Comment: Plunger lift

Corrective Action:

Date:

Facility ID: <u>279924</u>	Type: <u>WELL</u>	API Number: <u>045-11109</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
----------------------------	-------------------	------------------------------	-------------------	-------------------------

**Producing Well**

Comment: Plunger lift

Corrective Action:

Date:

Facility ID: <u>279925</u>	Type: <u>WELL</u>	API Number: <u>045-11110</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
----------------------------	-------------------	------------------------------	-------------------	-------------------------

**Producing Well**

Comment: Plunger lift

Corrective Action:

Date:

**Environmental**

**Spill/Remediation:**

Comment:

Corrective Action:  Date:

Emission Control Burner (ECB): YES

Comment:

Pilot: ON Wildlife Protection Devices (fired vessels): YES

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Gravel	Pass			
Gravel	Pass					
		Check Dams	Pass			
		Culverts	Pass			
		Ditches	Pass			

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401296000	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4158623">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4158623</a>
666803194	location	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4158619">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4158619</a>