

Loloff-Sand 1
API 05-123-12574
COGCC Site Inspection Photographs
June 5, 2017



Former production facility showing risers for product piping and remaining partially buried fiberglass produced water vessel. Standing in northeast corner of containment looking west.



2017/06/05

Former production facility showing risers for product piping and remaining partially buried fiberglass produced water vessel. Looking southeast.



Standing near former separator, looking west at plugged and abandoned Loloff-Sand 1 well in distance.



Former separator location with flowline riser visible.



Former produced water vessel with spilled used oil.



Water present in former produced water vessel.



Flowlines protruding from gravel pit wall. COGCC unable to inspect sand near flowline due to safety hazard of steep excavation wall.



Flowlines protruding from gravel pit wall. COGCC unable to inspect sand near flowline due to safety hazard of steep excavation wall.



Viewing excavation wall beneath produced water vault and used oil storage area.



Notebook for scale

Casing of plugged and abandoned Loloff-Sand 1 in active gravel pit. 8 ½ x 11 notebook for scale.