

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/24/2017

Submitted Date:

06/05/2017

Document Number:

674104061**FIELD INSPECTION FORM**Loc ID 320550 Inspector Name: Wolfe, Stephen On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 10548Name of Operator: HRM RESOURCES II LLCAddress: 410 17TH STREET #1600City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**3 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

| Contact Name    | Phone        | Email                | Comment |
|-----------------|--------------|----------------------|---------|
| Prohaska, April | 303-893-6621 | aprohaska@hrmres.com |         |
| Pape, Terry     | 970-768-5700 | tpape@hrmres.com     |         |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 287276      | WELL | PR     | 05/28/2007  | GW         | 001-09571 | LEECH 24-26   | EG          |

**General Comment:**2017 Flowline NTO Inspection

**Location**Overall Good: ☐

Emergency Contact Number:

Comment: Corrective Action: Date: Overall Good: ☐**Spills:**

|      |      |        |  |  |
|------|------|--------|--|--|
| Type | Area | Volume |  |  |
|------|------|--------|--|--|

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Equipment:**

|                    |   |       |                 |
|--------------------|---|-------|-----------------|
| Type: Flow Line    | #   |       | corrective date |
| Comment:           | IN USE: WELLHEAD- 2-2" steel risers, 1 wellsite to separator and 1 bradenhead to surface. SEPARATOR, PROCESS PIPING, TANKS and GAS SALES on Leech 1 location. Common battery for Leech 1, Leech 22-26, Leech 24-26 and Leech 14-26. |       |                 |
| Corrective Action: |   | Date: |                 |

**Venting:**

|                    |  |       |
|--------------------|--|-------|
| Yes/No             |  |       |
| Comment:           |  |       |
| Corrective Action: |  | Date: |

**Flaring:**

|                    |  |       |
|--------------------|--|-------|
| Type               |  |       |
| Comment:           |  |       |
| Corrective Action: |  | Date: |

**Inspected Facilities**Facility ID: 287276 Type: WELL API Number: 001-09571 Status: PR Insp. Status: EG**Flowline**

| #1  | Type: Well Site          | of Lines                      |       |
|---|--------------------------|-------------------------------|-------|
| <u>Flowline Description</u>   |                          |                               |       |
| Flowline Type: <u>Well Site</u>   | Size:                    | Material: <u>Carbon Steel</u> |       |
| Variance:   | Age:                     | Contents:                     |       |
| <u>Integrity Summary</u>  |                          |                               |       |
| Failures:   | Spills:                  | Repairs Made:                 |       |
| Coatings:   | H2S:                     | Cathodic Protection:          |       |
| <u>Pressure Testing</u>   |                          |                               |       |
| Witnessed: <u>No</u>  | Test Result: <u>Pass</u> | Charted: <u>No</u>            |       |
| <u>COGCC Rules(check all that apply)</u>  |                          |                               |       |
| <input type="checkbox"/> 1101. Installation and Reclamation <input type="checkbox"/> 1102. Operations, Maintenance, and Repair <input type="checkbox"/> 1103. Abandonment |                          |                               |       |
| <u>Comment:</u> <u>5/3/17 Flowline from wellhead to separator tested with wellhead fluids to 150 psi for 30 mins by ZD with HRM.</u>                                      |                          |                               |       |
| Corrective Action:  |                          |                               | Date: |

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description          | URL   |
|--------------|----------------------|---|
| 674104145    | Wellhead             | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4163469">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4163469</a> |
| 674104165    | Pressure test report | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4163470">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4163470</a> |