

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/05/2017

Submitted Date:

06/06/2017

Document Number:

675103658**FIELD INSPECTION FORM**

Loc ID 334599 Inspector Name: GRANAHAH, KYLE On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 100185Name of Operator: ENCANA OIL & GAS (USA) INCAddress: 370 17TH ST STE 1700City: DENVER State: CO Zip: 80202-**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
☐ FOLLOW UP INSPECTION REQUIRED
☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:17 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
, Encana		cogcc.inspections@encana.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
287313	WELL	PR	05/13/2007	GW	045-12963	SHORE 16-7 (PG16)	EG
288249	WELL	PR	05/28/2007	GW	045-13179	SHORE 16-6 (PG16)	EG
288250	WELL	PR	05/15/2007	GW	045-13178	SHORE 16-6BB(PG16)	EG
288251	WELL	PR	05/18/2007	GW	045-13177	SHORE 16-3 (PG16)	EG
288252	WELL	PR	05/24/2007	GW	045-13176	SHORE 16-3BB(PG16)	EG
288929	WELL	PR	05/26/2007	GW	045-13622	SHORE 16-7BB (PG16)	EG

General Comment:2017 Flowline NTO inspection 1000' buffer

LocationOverall Good: ☒

Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:	Present/complete		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Present/complete		
Corrective Action:		Date:	
Type	BATTERY		
Comment:	Present/complete		
Corrective Action:		Date:	

Emergency Contact Number:

Comment: Present/complete

Corrective Action:

Date: _____

Overall Good: ☒

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Equipment:			corrective date
Type: Gas Meter Run	# 1		
Comment:	39.44035/-108.00154		
Corrective Action:		Date:	
Type: Flow Line	#		
Comment:	IN USE; 6-3" steel risers from wells to separators. 4-3" steel risers from gas out separator to sales line. 6-2" steel risers from separator water/oil dump to tank battery. 1-3" steel riser from separator gas out to gas meter sales. 3-3" steel risers from separator water/oil dump to tank battery.		
Corrective Action:		Date:	
Type: Bird Protectors	# 4		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 6		
Comment:	39.44044/-108.00153		
Corrective Action:		Date:	
Type: Plunger Lift	# 6		
Comment:			
Corrective Action:		Date:	
Type: Flow Line	#		

Comment:	NOT IN USE; 1-1" steel gas line from separator to combustor. 1-4" steel riser from tank battery to combustor. 1-1" steel vapor blow down line from combustor to water/oil dump line at separator.		
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
CONDENSATE	2	300 BBLS	STEEL AST		39.440360,-108.001180	
Comment:						
Corrective Action:						Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities			
Facility ID: 287313	Type: WELL	API Number: 045-12963	Status: PR Insp. Status: EG
Producing Well			
Comment: PR - via plunger lift, no leaks/venting - bradenhead/well pressure remotely monitored.			
Corrective Action:		Date:	
Flowline			
#1	Type: Well Site	of Lines	
<u>Flowline Description</u> Flowline Type: <u>Well Site</u> Size: Material: Variance: Age: Contents:			
<u>Integrity Summary</u> Failures: Spills: Repairs Made: Coatings: H2S: Cathodic Protection:			
<u>Pressure Testing</u> Witnessed: Test Result: Charted:			
<u>COGCC Rules(check all that apply)</u> <input type="checkbox"/> 1101. Installation and Reclamation <input checked="" type="checkbox"/> 1102. Operations, Maintenance, and Repair <input type="checkbox"/> 1103. Abandonment			
Comment: NOT IN USE; 1-1" steel gas line from separator to combustor. 1-4" steel riser from tank battery to combustor. 1-1" steel vapor blow down line from combustor to water/oil dump line at separator. IN USE; 6-3" steel risers from wells to separators. 4-3" steel risers from gas out separator to sales line. 6-2" steel risers from separator water/oil dump to tank battery. 1-3" steel riser from separator gas out to gas meter sales. 3-3" steel risers from separator water/oil dump to tank battery.		Date:	
Corrective Action:			
Facility ID: 288249	Type: WELL	API Number: 045-13179	Status: PR Insp. Status: EG
Producing Well			
Comment: PR - via plunger lift, no leaks/venting - bradenhead/well pressure remotely monitored.			
Corrective Action:		Date:	
Facility ID: 288250	Type: WELL	API Number: 045-13178	Status: PR Insp. Status: EG
Producing Well			
Comment: PR - via plunger lift, no leaks/venting - bradenhead/well pressure remotely monitored.			
Corrective Action:		Date:	
Facility ID: 288251	Type: WELL	API Number: 045-13177	Status: PR Insp. Status: EG
Producing Well			
Comment: PR - via plunger lift, no leaks/venting - bradenhead/well pressure remotely monitored.			
Corrective Action:		Date:	
Facility ID: 288252	Type: WELL	API Number: 045-13176	Status: PR Insp. Status: EG
Producing Well			
Comment: PR - via plunger lift, no leaks/venting - bradenhead/well pressure remotely monitored.			
Corrective Action:		Date:	

Producing Well			
Comment:	PR - via plunger lift, no leaks/venting - bradenhead/well pressure remotely monitored.		
Corrective Action:		Date:	
Facility ID:	288929	Type:	WELL
API Number:	045-13622	Status:	PR
Insp. Status:	EG		
Producing Well			
Comment:	PR - via plunger lift, no leaks/venting - bradenhead/well pressure remotely monitored.		
Corrective Action:		Date:	

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass					
		Gravel	Pass			
		Compaction	Pass			
Compaction	Pass					

Comment: [No sediment flow evident](#)

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
675103659	Flowline photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4164437