

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/31/2017

Submitted Date:

06/01/2017

Document Number:

685200315

**FIELD INSPECTION FORM**

Loc ID 326580 Inspector Name: LABOWSKIE, STEVE On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 10000  
Name of Operator: BP AMERICA PRODUCTION COMPANY  
Address: 380 AIRPORT RD  
City: DURANGO State: CO Zip: 81303

**Findings:**

9 Number of Comments  
1 Number of Corrective Actions

Corrective Action Response Requested

**Contact Information:**

Contact Name	Phone	Email	Comment
Beebe, Sabre		sabre.beebe@bp.com	<a href="#">All Inspections</a>
Inspections, All		SanJuanCOGCC@bp.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
258261	WELL	PR	02/01/2001	GW	067-08344	MCMAHAN 2	PR

**General Comment:**

[Complaint inspection to close complaints 20040935 and 20040940. Additional mitigation in all directions has been done during tie since last COGCC sound survey, additional mitigation has resulted in aprox. 8 db\(a\) reduction as compared to previous readings.](#)

**Location**

Overall Good:

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	flammability 4 with adequate sized NFPA diamond		
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:			
Corrective Action:			Date: _____

<b>Good Housekeeping:</b>			
Type	WEEDS		
Comment:	new growth thistle observed on east edge of location and in several spots on access road (from east).		
Corrective Action:		Date:	
Type	DEBRIS		
Comment:	decomposing haybales near compressor from previous sound mitigation.		
Corrective Action:	remove per Rule 603.f, see guidance document for further details	Date:	07/01/2017

Overall Good:

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	OTHER		
Comment:	compressor now enclosed with sound walls		
Corrective Action:		Date:	

<b>Venting:</b>			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	

<b>Flaring:</b>			
Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 258261 Type: WELL API Number: 067-08344 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR

Corrective Action:

Date:

**Complaint**

Comment: Sound survey conducted to confirm compliance/respond to complaints #20040935 and 20040940 regarding noise. Sound walls have been installed completely around compressor. Sound was measured with a 3M Soundpro SE DL meter with a factory calibration date of 6/8/16. Meter was calibrated with a hand held calibrated calibrator before and after survey. Sound pressure was measured at 100' from soundwall in southeast direction. Winds were 03 mph out of east. 68 deg with clear skies, survey run from aprox. 11:15-30 AM. Avergae db(a) at 100' = 51.1 which extrapolates 40.2 db(a) at 350'.

Corrective Action:

Date:

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401298294	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4160825">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4160825</a>
685200316	sound meter at 100' from soundwall	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4160819">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4160819</a>
685200317	debris	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4160820">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4160820</a>
685200318	new growth noxious weeds, east side location	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4160821">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4160821</a>
685200319	sound survey report	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4160822">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4160822</a>