

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/07/2017

Submitted Date:

06/08/2017

Document Number:

679700465**FIELD INSPECTION FORM**

Loc ID 446700 Inspector Name: ALLISON, RICK On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 100322Name of Operator: NOBLE ENERGY INCAddress: 1625 BROADWAY STE 2200City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
☐ FOLLOW UP INSPECTION REQUIRED
☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:5 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Inspections, Noble		NBL_DJBU_Inspections@NB LENERGY.COM	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
446701	TANK BATTERY	AC	07/18/2016		-	MACBAIN 1	EI
449494	SPILL OR RELEASE	AC	03/22/2017		-	SPILL/RELEASE POINT	EI

General Comment:

LocationOverall Good: ☒

Emergency Contact Number:

Comment: [Present at battery](#)

Corrective Action:

Date: _____

Overall Good: ☒**Spills:**

Type	Area	Volume

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type TANK BATTERY

Comment: [Livestock 4 strand](#)

Corrective Action:

Date:

Equipment:

corrective date

Type: Emission Control Device

1

Comment:

Corrective Action:

Date:

Type: Gas Meter Run

1

Comment:

Corrective Action:

Date:

Type: Bird Protectors

2

Comment:

Corrective Action:

Date:

Type: Horizontal Heated Separator

1

Comment:

Corrective Action:

Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<50 BBLS	PBV CONCRETE		,

Comment: [Anchored](#)

Corrective Action:

Date:

Paint

Condition

Other (Content)

Other (Capacity)

Other (Type)

Berms

Inspector Name: ALLISON, RICK

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficent	Base Sufficent	Adequate	
Comment:					
Corrective Action:					Date:

Contents	#	Capacity	Type	Tank ID	SE GPS	
CRUDE OIL	1	300 BBLS	STEEL AST		,	

Comment:	Tank is anchored					
Corrective Action:						Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficent	Base Sufficent	Adequate	
Comment:					
Corrective Action:					Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities								
Facility ID:	446701	Type:	TANK	API Number: -	Status:	AC	Insp. Status:	EI
Facility ID:	449494	Type:	SPILL OR	API Number: -	Status:	AC	Insp. Status:	EI

Environmental**Spill/Remediation:**

Comment: COGCC Inspection related to spill ID 449494. Excavation that was open in March during release discovery has been filled. No waste stockpiled on or near the site. Several 1" piezometer/monitoring points are present. Covers are missing from some of the monitoring points in area east of battery and vulnerable to livestock damage. Operator is advised to secure monitoring points in accordance with Division of Water Resources Well Construction Rules.

Corrective
Action:

Date: _____

Emission Control Burner (ECB): _____

Comment:

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
679700466	View to west of excavated area and 1" MWs	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4165958
679700467	View of 1" MWs east of tank battery	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4165959