

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

05/23/2017

Submitted Date:

06/08/2017

Document Number:

674901680**FIELD INSPECTION FORM**
 Loc ID 325123 Inspector Name: Hughes, Jim On-Site Inspection ☐ 2A Doc Num:
Operator Information:OGCC Operator Number: 26625Name of Operator: ELM RIDGE EXPLORATION COMPANY LLCAddress: 12225 GREENVILLE AVE STE 950City: DALLAS State: TX Zip: 75243-**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:8 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Leonard, Mike		mike.leonard@state.co.us	
Fischer, Alex		alex.fischer@state.co.us	
Archuleta, Amy		aarchuleta@elmridge.net	
Lindeman, Terry	505-632-8048 EXT 210	tlindeman@elmridge.net	SW Inspection Reports

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
214065	WELL	PR	09/13/1959	GW	067-05362	MCELVAIN HARMON UNIT 1	EI

General Comment:

On May 23, 2017 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the Elm Ridge Exploration Co. McElvain Harmon #1. For the most recent field inspection report for this facility, please refer to document #685303001. COGCC West Environmental Supervisor Alex Fischer and Catamount representative Jacob Franchini were on location during this field inspection.

LocationOverall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:	Free standing sign located near wellhead.		
Corrective Action:		Date:	

Emergency Contact Number:

Comment: Operator contact information on well head sign.

Corrective Action: Date:

Overall Good: ☒

Spills:					
Type	Area	Volume			

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Fencing/:			
Type	PIT		
Comment:	Perimeter fencing around pit area.		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Dehydrator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Flow Line	# 1		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:		Date:	
Type: Deadman # & Marked	# 1		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<50 BBLs	Open Top		37.091760,-107.763147
Comment:	Expanded metal cover.				

Corrective Action:		Date:	
Paint			
Condition	Adequate		
Other (Content)			
Other (Capacity)	20 bbl.		
Other (Type)			
Berms			
Type	Capacity	Permeability (Wall)	Permeability (Base)
Earth	Inadequate	Walls Sufficient	Base Sufficient
Comment:	Secondary containment capacity is insufficient. Corrective action date taken from inspection document #685303001.		
Corrective Action:	Install or repair berms or other secondary containment to comply with Rule 605.a.(4).		Date: 06/11/2017
Venting:			
Yes/No	NO		
Comment:			
Corrective Action:			Date:
Flaring:			
Type			
Comment:			
Corrective Action:			Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Ditches	Pass					
Berms	Pass					
Compaction	Pass					

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PITType: Lined: NO Pit ID: 115630 Lat: 37.090979 Long: -107.761695Reference Point: Other: Length: Width: **Lining:**Liner Type: Liner Condition: Comment:

Corrective Action

Contact COGCC EPS regarding pit closure per Rule 905.b.Date: 06/19/2017c**Fencing:**Fencing Type: Livestock Fencing Condition: AdequateComment:

Corrective Action

Date: **Netting:**Netting Type: Netting Condition: Comment:

Corrective Action

Date: Anchor Trench Present: Oil Accumulation: 2+ feet Freeboard: Comment:

Corrective Action

Date: **COGCC Comments**

Comment	User	Date
On May 23, 2017 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the Elm Ridge Exploration Co. McElvain Harmon #1. For the most recent field inspection report for this facility, please refer to document #685303001. COGCC West Environmental Supervisor Alex Fischer and Catamount representative Jacob Franchini were on location during this field inspection. The purpose of this site visit was to discuss corrective actions required by the previous inspection with Catamount personnel. Submit a Site Investigation and Remediation Workplan regarding pit closure to SW EPS.	hughesj	06/08/2017

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
674901681	Fenced pit area.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4166276
674901682	Production equipment.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4166277