

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/22/2017

Submitted Date:

06/02/2017

Document Number:

674104045

FIELD INSPECTION FORM

Loc ID 320472 Inspector Name: Wolfe, Stephen On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10548
Name of Operator: HRM RESOURCES II LLC
Address: 410 17TH STREET #1600
City: DENVER State: CO Zip: 80202

Findings:

6 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Prohaska, April	303-893-6621	aprohaska@hrmres.com	
Pape, Terry	970-768-5700	tpape@hrmres.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
257053	WELL	PR	04/11/2000	GW	001-09406	MAUL 2	EG

General Comment:

[2017 Flowline NTO Inspection](#)

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

Type	#			corrective date
Flow Line				
Comment:	USED: Wellhead: 2-2" steel risers, 1 wellsite and 1 surface casing. SEPARATOR: 5-2" and 2-1" steel risers.			
Corrective Action:				Date: _____
Flow Line				
Comment:	UNUSED: 2-2" steel, adjacent to separator, not marked for abandonment.			
Corrective Action:				Date: _____

Venting:

Yes/No			
Comment:			
Corrective Action:			Date: _____

Flaring:

Type		
Comment:		
Corrective Action:		Date: _____

Inspected Facilities

Facility ID: 257053 Type: WELL API Number: 001-09406 Status: PR Insp. Status: EG

Flowline

#1	Type: Well Site	of Lines	
----	-----------------	----------	--

Flowline Description

Flowline Type: <u>Well Site</u>	Size:	Material:
Variance:	Age:	Contents:

Integrity Summary

Failures:	Spills:	Repairs Made:
Coatings:	H2S:	Cathodic Protection:

Pressure Testing

Witnessed: No Test Result: Pass Charted: No

COGCC Rules(check all that apply)

1101. Installation and Reclamation 1102. Operations, Maintenance, and Repair 1103. Abandonment

Comment: 5/4/17 Flowline from wellhead to separator tested with wellhead fluids to 190 psi for 30 mins by ZD with HRM.

Corrective Action: _____ Date: _____

#2	Type: Sales Line	of Lines	
----	------------------	----------	--

Flowline Description

Flowline Type: <u>Sales Line</u>	Size:	Material:
Variance:	Age:	Contents:

Integrity Summary

Failures:	Spills:	Repairs Made:
Coatings:	H2S:	Cathodic Protection:

Pressure Testing

Witnessed: No Test Result: Pass Charted: No

COGCC Rules(check all that apply)

1101. Installation and Reclamation 1102. Operations, Maintenance, and Repair 1103. Abandonment

Comment: 5/4/17 Sales line from separator to gas sales meter tested with wellhead fluids to 105 psi for 30 mins by ZD with HRM.

Corrective Action: _____ Date: _____

COGCC Comments

Comment	User	Date
<u>Advised operator that in addition to annual pressure testing, all active flowline risers that are not in service are required to be locked out and tagged out. Inactive flowlines need to be marked with flourescent paint, capped and scheduled for abandonment per Phase 1-Part 2 of the May 2, 2017 Flowline NTO.</u>	wolfes	05/29/2017

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401299165	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4161554

674104109	Wellhead	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4161550
674104110	Separator with risers	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4161551
674104111	Wellsite risers at separator	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4161552
674104112	Separator with ECD	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4161553