



**photo 1:** Facing northeast toward the former tank battery area. This area does not have adequate crop growth and contains predominately undesirable vegetation.



**photo 2:** View of undesirable vegetation and noxious weed growth (Kochia sp., Canada thistle) at the tank battery site.





**photo 3:** There is a pipe riser that remains at the former battery site Lat/Long:39.84499,-104.45152.



**photo 4:** Tag out has been applied to this valve at the pipe riser.





**photo 5:** Facing east toward the former access road. The crop growth has not adequately established along this area.



**photo 6:** Facing east toward the location. The crop growth has not adequately established along this area.





**photo 7:** There are noxious weeds growing at the location. (Canada thistle, Jointed goatgrass)



**photo 8:** Facing southwest toward the surrounding crop.