

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
401304837
Date Received:
06/09/2017

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 47120

Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP

Address: P O BOX 173779

City: DENVER State: CO Zip: 80217-3779

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Luke Reddy

970-515-1292

luke.reddy@anadarko.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 678800229

Inspection Date: 06/07/2017

FIR Submit Date: 06/07/2017

FIR Status: _____

Inspected Operator Information:

Company Name: KERR MCGEE OIL & GAS ONSHORE LP

Company Number: 47120

Address: P O BOX 173779

City: DENVER State: CO Zip: 80217-3779

LOCATION - Location ID: 318771

Location Name: WALTER J. RANKIN UNIT-63N67W Number: 19NWNW County: _____

Qtrqtr: NWN Sec: 19 Twp: 3N Range: 67W Meridian: 6
W

Latitude: 40.215835 Longitude: -104.938193

FACILITY - API Number: 05-123-00 Facility ID: 450945

Facility Name: WALTER J. RANKIN UNIT-63N67W Number: 19NWNW

Qtrqtr: NWN Sec: 19 Twp: 3N Range: 67W Meridian: 6
W

Latitude: 40.215835 Longitude: -104.938193

CORRECTIVE ACTIONS:

1 CA# 80926

Corrective Action: Comply with Phase I-Part 2 of the May 2, 2107 Flowline NTO.

Date: 05/30/2017

Response: CA COMPLETED

Date of Completion: 06/08/2017

Operator
Comment:

The existing risers on this location were inspected on 6/8/2017 by Anadarko staff and one 2 inch un-marked inactive riser was identified and properly marked with fluorescent paint to comply with Phase I-Part 2 of the May 2, 2017 Flowline NTO. There are now three 2 inch risers bull-plugged and marked for abandonment (with fluorescent paint) and three active 2 inch risers that are bull-plugged and tagged as "Active." Please reference

attached photos.

COGCC Decision: _____

COGCC
Representative: _____

OPERATOR COMMENT AND SUBMITTAL

Comment: The existing risers on this location were inspected on 6/8/2017 by Anadarko staff and one 2 inch un-marked inactive riser was identified and properly marked with fluorescent paint to comply with Phase I-Part 2 of the May 2, 2017 Flowline NTO. There are now three 2 inch risers bull-plugged and marked for abandonment (with fluorescent paint) and three active 2 inch risers that are bull-plugged and tagged as "Active." Please reference attached photos.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Luke Reddy

Signed: _____

Title: Regulatory Specialist

Date: 6/9/2017 12:17:48 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

Document Number **Description**

401304884	Inactive / Active lines
-----------	-------------------------

Total Attach: 1 Files