

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/08/2017

Submitted Date:

06/09/2017

Document Number:

685303264**FIELD INSPECTION FORM**Loc ID 320863 Inspector Name: St John, William (Cal) On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 26625Name of Operator: ELM RIDGE EXPLORATION COMPANY LLCAddress: 12225 GREENVILLE AVE STE 950City: DALLAS State: TX Zip: 75243-**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:6 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Redmond, Nolan	720-484-2347	Inspections@catamountep.com	All Inspections
Archuleta, Amy		aarchuleta@elmridge.net	SW Inspection Reports
Lindeman, Terry	505-632-8048 EXT 210	tlindeman@elmridge.net	SW Inspection Reports

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
205261	WELL	PR	07/07/2000	GW	007-06140	PARGIN MOUNTAIN UNIT 11	PR

General Comment:[See link at end of report for path to downloadable pictures. Witnessed MIT 06/08/2017.](#)

LocationOverall Good: ☐

Emergency Contact Number:

Comment: Corrective Action: Date: Overall Good: ☐**Spills:**

Type	Area	Volume		

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	OTHER	STEEL AST		,	
Comment:	<input type="text"/>					
Corrective Action:	<input type="text"/>				Date:	<input type="text"/>

Paint

Condition	Adequate	<input type="text"/>
Other (Content)	<input type="text"/>	
Other (Capacity)	20 BBLS	<input type="text"/>
Other (Type)	<input type="text"/>	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:	Weeds inside containment berms. Corrective action completed.			
Corrective Action:	<input type="text"/>			Date: <input type="text"/>

Venting:

Yes/No	<input type="text"/>	<input type="text"/>
Comment:	<input type="text"/>	
Corrective Action:	<input type="text"/>	Date: <input type="text"/>

Flaring:

Type	<input type="text"/>	<input type="text"/>
Comment:	<input type="text"/>	
Corrective Action:	<input type="text"/>	Date: <input type="text"/>

Inspected FacilitiesFacility ID: 205261 Type: WELL API Number: 007-06140 Status: PR Insp. Status: PR**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: _____

Comment: Production records indicate last reported production was July 2014. Inspection status reflects PR but the well production report shows the well has been reported as SI since August 2014. MIT completed to comply with Rule 326.b.

Well was pressured up to initial test pressure of 405 psi. Pressure was stabile and 405 psi was maintained throughout extended 30 minute test period. See attached photo documentation. Operator will submit required Form 21 and chart.

Corrective Action: _____

Date: _____

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
685303278	Wellhead sign.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4167462
685303279	Tank contianment with weeds removed.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4167463
685303280	Chart 5 min.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4167464
685303281	Chart 10 min.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4167465
685303282	Chart 20 min.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4167466
685303283	Chart 30 min.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4167467