

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/31/2017

Submitted Date:

06/05/2017

Document Number:

674603352**FIELD INSPECTION FORM**

Loc ID 319253 Inspector Name: Maclaren, Joe On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 47120Name of Operator: KERR MCGEE OIL & GAS ONSHORE LPAddress: P O BOX 173779City: DENVER State: CO Zip: 80217-**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
☐ FOLLOW UP INSPECTION REQUIRED
☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:3 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	
,		cogccinspections@anadarko.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
243158	WELL	TA	01/01/2017	GW	123-10949	CARL A. MILLER D 2	EG

General Comment:

COGCC Engineering Integrity Inspection performed on May 31st, 2017 in response to initial form 19 spill report Doc #401292705 received on 05/26/2017 that outlines: During abandonment activities at the Carl A Miller D #2 tank battery, soil with historical petroleum hydrocarbon impacts was encountered. Details of observations made during this field inspection are available in the comment section of this report. Photo's uploaded and can be accessed via link(s) at the end of this report.

Inspected Facilities

Facility ID: 243158 Type: WELL API Number: 123-10949 Status: TA Insp. Status: EG

COGCC Comments

Comment	User	Date
Excavation and remediation activities were in progress at the time of this field inspection. There is a 4" Kerr McGee natural gas gathering line exposed in the excavation. This gas line appears to be "bent" as a result of equipment contact; however, based on a conversation with the contractor on site the pipeline was unearthed in the current condition. As discussed, There was no contact or damage to this pipeline as a result of this field remediation project. (Note: *Ensure integrity of this pipeline is not compromised during the remainder of this project. Contact Kerr McGee gathering as needed/ required regarding this gas gathering pipeline). There is also a gas meter run and pipeline pig station located approximately 50' east of the spill location where the cleanup work is being completed.	maclarej	06/05/2017
As outlined on supplemental spill report doc #401296369 received on 06/01/2017: During abandonment activities at the Carl A Miller D #2 tank battery, soil with historical petroleum hydrocarbon impacts was encountered. The volume of the release is unknown. The tank battery was abandoned and the site will be restored to pre-release grade.	maclarej	06/05/2017

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401300202	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4162621
674603366	Exposed 4" gathering pipeline in excavation	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4162616
674603367	Meter run and pig launcher (gas gathering)	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4162617
674603368	Closer view of 4" gas gathering pipeline	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4162618