

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/01/2017

Submitted Date:

06/05/2017

Document Number:

674603354**FIELD INSPECTION FORM**
 Loc ID 317901 Inspector Name: Maclaren, Joe On-Site Inspection ☐ 2A Doc Num: _____
Operator Information:OGCC Operator Number: 100322Name of Operator: NOBLE ENERGY INCAddress: 1625 BROADWAY STE 2200City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:3 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Gintautas, Peter		peter.gintautas@state.co.us	
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	
,		NBL_DJBU_Inspections@NB LENERGY.COM	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
240145	WELL	PR	07/14/2000	OW	123-07933	APOLLO 1	EG

General Comment:

COGCC Engineering Integrity Inspection performed on June 1st, 2017 in response to initial form 19 spill report Doc #401287639 received on 05/19/2017 that outlines: During operations the firetube on the separator developed a leak at the Apollo 1, LH1 tank battery location. The location is shut in and excavation of impacted soil will be scheduled the week of May 22-26, 2017. The details of observations made during this field inspection are available in the equipment and comment sections of this report. Photo's uploaded and can be accessed via link(s) at the end of this report.

LocationOverall Good: ☐

Emergency Contact Number:

Comment: Corrective Action: Date: Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Equipment:**

Type: Horizontal Heated Separator	# 1		corrective date
Comment:	Note: Document and retain records of root cause of failure evaluation, measures taken to prevent the problem from reoccurring and description of repairs completed (*on supplemental form 19).		
Corrective Action:		Date:	

Venting:

Yes/No		
Comment:		
Corrective Action:		Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 240145 Type: WELL API Number: 123-07933 Status: PR Insp. Status: EG

COGCC Comments

Comment	User	Date
Excavation equipment has been mobilized to location. There was no equipment repair or site remediation work in progress at the time of this field inspection.	maclarej	06/05/2017

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401300043	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4162511
674603364	Signage and view of horizontal separator	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4162507
674603365	Horizontal separator on location	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4162508