

**FORM  
INSP**Rev  
X/15

# State of Colorado

## Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

06/12/2017

Submitted Date:

06/12/2017

Document Number:

666803225**FIELD INSPECTION FORM**
 Loc ID 322325 Inspector Name: Murray, Richard On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_
**Operator Information:**OGCC Operator Number: 10550Name of Operator: MUSTANG RESOURCES LLCAddress: 1660 LINCOLN STREET SUITE 1450City: DENVER State: CO Zip: 80264**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**7 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Austin, Chris	970-756-1696	caustin@mustangresourcesllc.com	
Couts, Brandon		bcoutts@mustangresourcesllc.com	Field Operations

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
210278	WELL	PR	12/01/2016	GW	045-06034	JUHAN RULISON UNIT 34-94-6S-94W	PR

**General Comment:**2017 Flowline NTO Inspection 1000' Buffer

**Location**Overall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☒**Spills:**

Type

Area

Volume

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

corrective date

Type: Gas Meter Run

# 1

Comment: 39.479740/-107.874346

Corrective Action:

Date:

Type: Flow Line

#

Comment: In use; 1-2" steel risers at wellhead, 1-2" steel risers at gas meter run

Corrective Action:

Date:

Type: Flow Line

#

Comment: unused 1-2" see photo

Corrective Action:

Date:

Type: Other

# 0

Comment: Wellhead-39.479827/-107.874483

Corrective Action:

Date:

**Venting:**

Yes/No NO

Comment:

Corrective Action:

Date:

**Flaring:**

Type

Comment:

Corrective Action:

Date:

<b>Inspected Facilities</b>			
Facility ID: <u>210278</u>	Type: <u>WELL</u>	API Number: <u>045-06034</u>	Status: <u>PR</u> Insp. Status: <u>PR</u>
<b>Producing Well</b>			
Comment:	<u>producing</u>		
Corrective Action:		Date:	

Environmental	
<b>Spill/Remediation:</b>	
Comment:	
Corrective Action:	Date:
Emission Control Burner (ECB): NO	
Comment:	
Pilot:	Wildlife Protection Devices (fired vessels):

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Compaction	Pass			
Compaction	Pass					

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
666803226	Mustang NTO	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4168791">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4168791</a>
666803227	Mustang NTO 2	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4168792">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4168792</a>