

Location

Overall Good:

Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:	Produced water vault not labeled.		
Corrective Action:	Install sign to comply with Rule 210.d.	Date:	07/07/2017
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:	303-481-2844		
Corrective Action:			Date: _____

Overall Good:

Spills:				
Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:			
Type	TANK BATTERY		
Comment:	barbed wire		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	steel panel		
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	barbed wire		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:		Date:	
Type: Flow Line	# 15		

Comment:	IN USE: 1-2" steel riser at wellhead GPS 39.66810, -104.46252; 5-2" steel risers at separator GPS 39.67043, -104.46507; GMR 1-3" steel riser and 1-2" steel riser GPS 39.67043, -104.46516 and 39.67044, -104.46514; 2-2" steel risers at vault GPS 39.670511, -104.46522; tanks, 1-2" hot oil steel riser line GPS 39.67055, -104.46539, East tank 2-2" steel risers GPS 39.67055, -104.46539, West tank 2-2" steel risers GPS 39.67054, -104.46543. Contacted Operator who said that the double riser configuration would be chanded to one riser.			Date:
Corrective Action:				Date:
Type: Gas Meter Run	# 1			
Comment:				Date:
Corrective Action:				Date:
Type: Flow Line	# 2			
Comment:	NOT IN USE: 1-1" steel riser at wellhead, 1-2" steel riser at treater, flagged.			Date:
Corrective Action:				Date:
Type: Bird Protectors	# 1			
Comment:	On HHS. Need on open pipe ends at vault. Contacted operator about bird protectors.			Date:
Corrective Action:				Date:
Type: Horizontal Heated Separator	# 1			
Comment:	bermed			Date:
Corrective Action:				Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1		BV CONCRETE		,
Comment:					
Corrective Action:					Date:

Paint

Condition					
Other (Content)					
Other (Capacity)					
Other (Type)					

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Insufficient	Inadequate
Comment:	weeds inside berms			
Corrective Action:	Comply with Rule 603.f using the Rule 603.f guidance document for further details.			Date: 07/07/2017

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	2	300 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition					
Other (Content)					

Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient	Base Insufficient	Inadequate	
Comment: Weeds inside tank battery berms.					
Corrective Action: Comply with Rule 603.f using the Rule 603.f guidance document for further details.				Date:	<u>07/07/2017</u>

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 204915 Type: WELL API Number: 005-07000 Status: SI Insp. Status: EG

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: Shut In since Jan 2017.

Corrective Action: _____

Date: _____

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass					
Gravel	Pass					

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401301990	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4164355
673715566	Bison Bennett A-2	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4164350