

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/24/2017

Submitted Date:

06/05/2017

Document Number:

674104065**FIELD INSPECTION FORM**

Loc ID      Inspector Name:      On-Site Inspection ☐  
 319811      Wolfe, Stephen      2A Doc Num: \_\_\_\_\_

**Operator Information:**OGCC Operator Number: 10548Name of Operator: HRM RESOURCES II LLCAddress: 410 17TH STREET #1600City: DENVER      State: CO      Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION  
☐ FOLLOW UP INSPECTION REQUIRED  
☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**6 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Pape, Terry	970-768-5700	tpape@hrmres.com	
Prohaska, April	303-893-6621	aprohaska@hrmres.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
201446	WELL	PR	02/01/2017	GW	001-06849	MERKOWITZ 1	EG

**General Comment:**[2017 Flowline NTO Inspection](#)

**Location**Overall Good: ☐

Emergency Contact Number:

Comment: Corrective Action: Date: Overall Good: ☐**Spills:**

Type	Area	Volume		

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Equipment:**

Type: Flow Line	#		corrective date
Comment:	IN USE: WELLHEAD- 2-2" steel risers, 1 wellsite and 1 surface casing. SEPARATOR- 3-2" steel risers. PROCESS PIPING- 1-2" steel riser to ECD, 2-1" steel risers, fuel line from separator to ECD. GAS SALES- 1-2" steel riser.		
Corrective Action:			Date:
Type: Flow Line	#		
Comment:	NOT IN USE: 1-2" riser at ECD, not connected or marked.		
Corrective Action:			Date:

**Venting:**

Yes/No		
Comment:		
Corrective Action:		Date:

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**

Facility ID: 201446 Type: WELL API Number: 001-06849 Status: PR Insp. Status: EG

**Flowline**

#1	Type: Well Site	of Lines	
----	-----------------	----------	--

Flowline Description

Flowline Type: Well Site Size: Material: Carbon Steel  
 Variance: Age: Contents:

Integrity Summary

Failures: Spills: Repairs Made:  
 Coatings: H2S: Cathodic Protection:

Pressure Testing

Witnessed: No Test Result: Pass Charted: No

COGCC Rules(check all that apply)

☐ 1101. Installation and Reclamation ☐ 1102. Operations, Maintenance, and Repair ☐ 1103. Abandonment

Comment: 4/26/17 Flowline from wellhead to separator tested with wellhead fluids to 220 psi for 15 mins by ZD with HRM.

Corrective Action: Date:

#2	Type: Sales Line	of Lines	
----	------------------	----------	--

Flowline Description

Flowline Type: Sales Line Size: Material:  
 Variance: Age: Contents:

Integrity Summary

Failures: Spills: Repairs Made:  
 Coatings: H2S: Cathodic Protection:

Pressure Testing

Witnessed: No Test Result: Pass Charted: No

COGCC Rules(check all that apply)

☐ 1101. Installation and Reclamation ☐ 1102. Operations, Maintenance, and Repair ☐ 1103. Abandonment

Comment: 4/26/17 Sales line from separator to gas sales meter tested with wellhead fluids to 100 psi for 30 mins by ZD with HRM.

Corrective Action: Date:

**COGCC Comments**

Comment	User	Date
<u>Identify 2" riser at ECD and test and lock out/tag out or mark for abandonment.</u>	wolfes	06/05/2017

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401301199	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4163548">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4163548</a>
674104154	Tank	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4163486">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4163486</a>

674104155	Separator	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4163487">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4163487</a>
674104156	Separator	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4163488">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4163488</a>
674104157	Process piping	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4163489">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4163489</a>
674104158	Process piping	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4163490">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4163490</a>
674104159	Pressure test report	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4163491">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4163491</a>
674104160	Wellhead	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4163492">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4163492</a>