

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/05/2017

Submitted Date:

06/06/2017

Document Number:

675103654

FIELD INSPECTION FORM

Loc ID 334758 Inspector Name: GRANAHAN, KYLE On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 100185
Name of Operator: ENCANA OIL & GAS (USA) INC
Address: 370 17TH ST STE 1700
City: DENVER State: CO Zip: 80202-

Findings:

13 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

Contact Information:

| Contact Name | Phone | Email | Comment |
|--------------|-------|------------------------------|---------|
| , Encana | | cogcc.inspections@encana.com | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|----------------------|-------------|
| 293984 | WELL | PR | 02/27/2008 | GW | 045-15194 | TONDER 17-1 (PA17) | EG |
| 294174 | WELL | PR | 03/03/2008 | GW | 045-15296 | TONDER 17-1BB (PA17) | EG |

General Comment:

[2017 Flowline NTO inspection 1000' buffer](#)

Location

Overall Good:

| Signs/Marker: | | | |
|----------------------|----------------------|--|-------|
| Type | WELLHEAD | | |
| Comment: | Present/complete | | |
| Corrective Action: | | | Date: |
| Type | BATTERY | | |
| Comment: | Present/complete | | |
| Corrective Action: | | | Date: |
| Type | TANK LABELS/PLACARDS | | |
| Comment: | Present/complete | | |
| Corrective Action: | | | Date: |

| | | | |
|---------------------------|------------------|--|-------------|
| Emergency Contact Number: | | | |
| Comment: | Present/complete | | Date: _____ |
| Corrective Action: | | | |

Overall Good:

| Spills: | | | |
|----------------|------|--------|--|
| Type | Area | Volume | |
| | | | |

In Containment: No

Comment:

Multiple Spills and Releases?

| Equipment: | | | corrective date |
|---------------------------------|---|--|-----------------|
| Type: Ancillary equipment | # 1 | | |
| Comment: | Chem tote with secondary containment. | | |
| Corrective Action: | | | Date: |
| Type: Plunger Lift | # 2 | | |
| Comment: | | | |
| Corrective Action: | | | Date: |
| Type: Bird Protectors | # 1 | | |
| Comment: | | | |
| Corrective Action: | | | Date: |
| Type: Gas Meter Run | # 1 | | |
| Comment: | 39.44441/-108.01204 | | |
| Corrective Action: | | | Date: |
| Type: Flow Line | # | | |
| Comment: | IN USE; 2-3" steel risers from wells to separators. 2-3" steel risers from gas out separator to sales line. 2-2" steel risers from separator water/oil dump to tank battery. 1-3" steel riser from separator gas out to gas meter sales. 1-3" steel risers from separator water/oil dump to tank battery. | | |
| Corrective Action: | | | Date: |
| Type: Vertical Heated Separator | # 2 | | |

| | | | |
|--------------------|---------------------|-------|--|
| Comment: | 39.44433/-108.01211 | | |
| Corrective Action: | | Date: | |

Tanks and Berms:

| Contents | # | Capacity | Type | Tank ID | SE GPS |
|--------------------|---|----------|-----------|---------|-----------------------|
| CONDENSATE | 1 | 300 BBLs | STEEL AST | | 39.444610,-108.012120 |
| Comment: | | | | | |
| Corrective Action: | | | | | Date: |

Paint

| | | |
|------------------|----------|--|
| Condition | Adequate | |
| Other (Content) | | |
| Other (Capacity) | | |
| Other (Type) | | |

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|----------|---------------------|---------------------|-------------|
| Metal | Adequate | Walls Sufficient | Base Sufficient | Adequate |
| Comment: | | | | |
| Corrective Action: | | | | Date: |

Venting:

| | | |
|--------------------|----|-------|
| Yes/No | NO | |
| Comment: | | |
| Corrective Action: | | Date: |

Flaring:

| | |
|--------------------|-------|
| Type | |
| Comment: | |
| Corrective Action: | Date: |

Inspected Facilities

Facility ID: 293984 Type: WELL API Number: 045-15194 Status: PR Insp. Status: EG

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: EQUIPMENT ONSITE

Comment: Well SI at time of inspection - plunger lift on wellhead, bradenhead/well pressure remotely monitored

Corrective Action: Date: _____

Flowline

| | | | |
|----|-----------------|----------|--|
| #1 | Type: Well Site | of Lines | |
|----|-----------------|----------|--|

Flowline Description

Flowline Type: Well Site Size: _____ Material: _____
 Variance: _____ Age: _____ Contents: _____

Integrity Summary

Failures: _____ Spills: _____ Repairs Made: _____
 Coatings: _____ H2S: _____ Cathodic Protection: _____

Pressure Testing

Witnessed: _____ Test Result: _____ Charted: _____

COGCC Rules(check all that apply)

1101. Installation and Reclamation 1102. Operations, Maintenance, and Repair 1103. Abandonment

Comment: IN USE; 2-3" steel risers from wells to separators. 2-3" steel risers from gas out separator to sales line. 2-2" steel risers from separator water/oil dump to tank battery. 1-3" steel riser from separator gas out to gas meter sales. 1-3" steel risers from separator water/oil dump to tank battery.

Corrective Action: Date: _____

Facility ID: 294174 Type: WELL API Number: 045-15296 Status: PR Insp. Status: EG

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: EQUIPMENT ONSITE

Comment: Well SI at time of inspection - plunger lift on wellhead, bradenhead/well pressure remotely

Corrective Action: Date: _____

Reclamation - Storm Water - Pit

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Berms | Pass | | | | | |
| Compaction | Pass | | | | | |
| Gravel | Pass | | | | | |

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|----------------------|---|
| 401302073 | INSPECTION SUBMITTED | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4164440 |
| 675103655 | Flowline photo log | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4164435 |